

www.vabfleetservices.be Date: 18/07/2017 1/5

BYG3PQ

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	174860 KM
File nr. :	1419682	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FCW645 / VF1JZ14M649018	3423 /	yr of constructionr :	/
E-File nr. :		First registration :	28/05/2013
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:	N	Environment Class:	EURO 5
Customer company:	BELGACOM INS/FLEET NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

Variant car:	MONOVOLUME	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	-	ı	

Metallic paint:

Yes



www.vabfleetservices.be Date: 18/07/2017 2/5

Original registr. number :	OK		Service manual :	OK	
Cert. of reg. / Part 1:	OK		Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		[x]
Warning vest:	OK		Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	
Fuel card :		[x]	Car radio :	OK	
Mobile phone kit :			Extinguisher :	OK	
			Warning triangle :	OK	
First aid kit :	OK		Oil level :	OK	
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

		[x] V	Vidth]	Height		Туре		Rim	Index
Wheel RES:	[x]	MICHELIN	Tyre:	OK [x	x] >6/	Rim:		/	Hubcap:	
Wheel RR:	[x]	VREDESTEIN	Tyre:	OK [x	x] >6/	Rim:	[x]	/	Hubcap: [x	SCRATCHED
Wheel FR:	[x]	VREDESTEIN	Tyre:	OK	4-6 /	Rim:		/	Hubcap: [x]] SCRATCHED
Wheel RL:	[x]	VREDESTEIN	Tyre:	OK [x	x] >6/	Rim:	[x]	/	Hubcap:	
Wheel FL:	[x]	VREDESTEIN	Tyre:	OK	4-6 /	Rim:		/	Hubcap: [x	BROKEN / CRACKED

_	[x]	Width	Height	Type	Rim	Index
	Front tyre	205	60	R	16	W
	Rear tyre	205	60	R	16	W
_						

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 18/07/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

31	A1U5: ACCEPTABLE	USAGE DAMA	NGE		
Во	dywork \& windows				
[x]	REAR MUDGUARD/LEFT/REAR		DENT	2X	
[x]	REAR MUDGUARD/LEFT/FRONT		DENT		
[x]	REAR DOOR/LEFT/FRONT		DENT		
[x]	REAR DOOR/RIGHT/CORNER/BELOW		SCRATCH WITH PAINT DAMAGE	INT.	
[x]	FRONT DOOR/LEFT/CENTER		DENT		
[x]	FRONT THRESHOLD/LEFT/FRONT		OTHER DAMAGES		
[x]	FRONT DOOR/RIGHT/REAR		DENT		
[x]	BONNET/CENTER/LEFT/FRONT		CHIPS		
Inte	erior				
[x]	CENTER CONSOLE		OTHER DAMAGES		
	SEAT FL		OTHER DAMAGES		
[x]	BOOT LID IN		SCRATCHED		
Ac	cessories and others				
	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH WITH PAINT DAMAGE		
ST	ATUS: NOT ACCEPTA	BLE			
Во	dywork \& windows				
[x]	FRONT BUMPER/LEFT/CORNER		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
	3 0 LU =0.00 EUR	0 EUR		50 %	
Inte	erior				
[x]	DOOR IN REAR L		OTHER DAMAGES		
		Repair paint - LI	New paint - E	Depr.	Total
	1 0 LU =0.00 EUR	0 EUR		50 %	



www.vabfleetservices.be Date: 18/07/2017 4/5

_	•	ı_	_		
		n	0	rc	
	44		•		

 $HUB\;CAP\;FL$

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

ces					
Number	Code	Description	Unit price	Depr.	Total
1 1	SPEAKER GRID		18.00 EUR	50 %	18.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2 1	WHEEL CAP		30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3 1	BUMPER GRID		20.00 EUR	50 %	20.00 EUR

1	2	3	4	5	6	7	8	9	10
18.00	30.00	20.00	0	0	0	0	0	0	0
9.00	15.00	10.00	0	0	0	0	0	0	0

	i			
		GENERAL	TRADITIONAL	INNOVATIVE
68.00		0	68.00	0
34.00	NA Deprec.		BG: 0	HOG: 0
	0.00%			
34.00	TOTAL			



www.vabfleetservices.be Date: 18/07/2017 5/5

[x] = Status Modification

Pictures: No							
CIRCUMST	ANCES			NORMAL CONC	LUSION		
Extra Time :	ne: 0 min Reason:		Towing time : Reason :		0 min		
NOT EXECUTED : Reason :	No	<u> </u>					
Remark :	NAVI OK [x]						
Prices in EUR with	hout VAT						
Authorized by customer :				Executed by VAB Fleet	Services		
Remark authorized cus	stomer :						
Date :	18/07/2017	Hour :	11:26				
Company:							
Executed by VAB Fleet Services							
E-Mail :	@						
Signature authorized by	customer		_				
_							