

CLJEQW

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	176703 KM
File nr. :	1437603	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FQH751 / WBAVY11070VW90591 /		yr of constructionr :	/
E-File nr. :		First registration :	23/09/2013
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / X1	Fuel type :	DIESEL
Object nr. :	940	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	THERABEL PHARMA SA	Co2:	126g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	X1 sDrive16 116PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :		
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :		
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/	Hubcap :	
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :	[x]	/	Hubcap :	[x] SCRATCHED
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		225	50	R	17	V
Rear tyre		225	50	R	17	V

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/RIGHT/CENTER	OTHER DAMAGES	POLIEREN
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	WINDSCREEN/RIGHT	CHIPS	
[x]	FRONT MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	REAR BUMPER/LEFT/LEFT		DENT			
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	REAR MUDGUARD/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE		+DEUK	
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		+DEUK	
		Repair paint - LI	New paint - E	Depr.	Total	
6	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	FRONT BUMPER/LEFT/CORNER		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	29.16 EUR

HUB CAP REAR RIGHT

Repair paint - LI

New paint - E

Depr.

Total

2 0 LU =0.00 EUR

50 %

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
29.16	30.00	211.80	308.20	211.80	308.20	0	0	0	0
29.16	15.00	105.90	154.10	105.90	154.10	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
29.16	1070.00	0	1099.16
HOG: 0	BG: 0		NA Deprec. 564.16
			0.00%
			TOTAL 564.16

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/09/2017 Hour : 09:34 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	