

6ARND6

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	6062 KM
File nr. :	1261251	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LLG054 / SAJBB4BN6GCRY04798 /		yr of constructionr :	/
E-File nr. :		First registration :	19/10/2015
VFS-nr. :		Color :	BLACK
Make + Model :	JAGUAR / XF	Fuel type :	DIESEL
Object nr. :	47266	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	PIDPA CVBA	Co2:	109g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1999
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	4
HP:	175	kW:	129
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :	OK	[x]	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	V
Rear tyre	225	55	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	ROOF /FRONT/LEFT/CENTER	OTHER DAMAGES	CHEMISCHE INWERKING
	Repair paint - LI	New paint - E	Depr. Total
1	0 LU =0.00 EUR	577.80 EUR	50 % 577.80 EUR

[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	CHEMISCHE INWERKING
	Repair paint - LI	New paint - E	Depr. Total
1	0 LU =0.00 EUR	348.09 EUR	50 % 348.09 EUR

1	2	3	4	5	6	7	8	9	10
925.89	0	0	0	0	0	0	0	0	0
462.94	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	925.89	0	925.89
HOG: 0	BG: 2		NA Deprec. 462.94
			0.00%
			TOTAL 462.94

APPRAISAL

www.vabfleetservices.be

Date : 01/04/2016

4/4

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 01/04/2016 Hour : 16:28	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	