

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|----------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 78938 |
| File nr. : | 1433468 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1ERR022 / YV1FW84A1D1128668 / | | yr of constructionr : | 2013 / 00 |
| E-File nr. : | | First registration : | 04/03/2013 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | VOLVO / V60 | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | BELGACOM INS/FLEET NV | Co2: | 119g/km |
| Driver : | | Remote controls: | 1 |
| Covering : | TISSUE | Number keys : | 1 [x] |
| Vehicle kind : | | Seats (minivan) : | 0 |
| Vehicle type : | V60 D2 Kinetic St/St 115PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1560 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 114 | kW: | 84 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |

General condition:

| | |
|--------------------------------|---------------------------|
| Original registr. number : OK | Service manual : OK [x] |
| Cert. of reg. / Part 1: OK [x] | Cert. of conformity : OK |
| Cert. of reg. copy / Part 2: | Insurance certificate : |
| Warning vest : | Transport licence : |
| Tax certificate : | Navigation CD/SD/DVD |
| Fuel card : | Car radio : OK [x] |
| Mobile phone kit : | Extinguisher : OK [x] |
| First aid kit : OK [x] | Warning triangle : OK [x] |
| Jack, wheelspanner : | Oil level : OK [x] |
| | Filled up : 0 |

Wheels and tyres: Summer tires

| |
|--|
| Wheel FL: [x] FIRESTONE Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RL : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap : |
| Wheel FR : [x] FIRESTONE Tyre : [x] OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RR : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RES: [x] Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 235 | 45 | R | 17 | Y |
| Rear tyre | 235 | 45 | R | 17 | Y |

Remark :

Wheels and tyres:

| |
|---|
| Wheel FL: Tyre : OK / Rim : / Hubcap : |
| Wheel RL : Tyre : OK / Rim : / Hubcap : |
| Wheel FR : Tyre : OK / Rim : / Hubcap : |
| Wheel RR : Tyre : OK / Rim : / Hubcap : |
| Wheel RES: Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | |
|-----|--------------------------|---------------------------|----------|
| [x] | REAR MUDGUARD/LEFT/FRONT | DENT | |
| [x] | ROOF STYLE/CENTER/LEFT | DENT | |
| [x] | FRONT DOOR/LEFT/REAR | SCRATCH WITH PAINT DAMAGE | |
| [x] | FRONT DOOR/LEFT/CENTER | SCRATCH WITH PAINT DAMAGE | |
| [x] | BONNET/CENTER/LEFT | OTHER DAMAGES | ISOLATIE |

Interior

| | | |
|-----|-----------------|-------|
| [x] | SEAT FL | STAIN |
| [x] | SEAT FR | STAIN |
| [x] | SEAT REAR L | STAIN |
| [x] | SEAT REAR RIGHT | STAIN |
| [x] | ROOF UPHOLSTERY | STAIN |

Accessories and others

| | | |
|-----|------------------|------------------|
| [x] | REARWINDOW WIPER | BROKEN / CRACKED |
|-----|------------------|------------------|

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | |
|-----|-------------------------------|---------------------------|----------------------|--------------|
| [x] | REAR BUMPER/SIDE/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE | | |
| | | Repair paint - LI | New paint - E | Depr. |
| | | | | Total |
| 4 | 0 LU =0.00 EUR | 211.80 EUR | | 50 % |
| | | | | 211.80 EUR |

| | | | | |
|-----|-----------------------|--------------------------|----------------------|--------------|
| [x] | REAR DOOR/LEFT/CENTER | DENT | | |
| | | Repair paint - LI | New paint - E | Depr. |
| | | | | Total |
| 3 | 0 LU =0.00 EUR | 318.35 EUR | | 50 % |
| | | | | 318.35 EUR |

| | | | | |
|-----|------------------------|--------------------------|----------------------|--------------|
| [x] | WINDSCREEN/CENTER/LEFT | WINDOW DAMAGE | | |
| | | Repair paint - LI | New paint - E | Depr. |
| | | | | Total |
| 2 | I 1 i-vab-herstr-01 | WINDOW REPAIR | 58.80 EUR | 50 % |
| | | | | 58.80 EUR |

| [x] FRONT MUDGUARD/LEFT/FRONT | | SCRATCH WITH PAINT DAMAGE | | | |
|-------------------------------|-----------------|---------------------------|---------------|-------|------------|
| Number | Code | Description | Unit price | Depr. | Total |
| 1 | I 1 i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | | 115.56 EUR |
| [x] FRONT BUMPER/LEFT/SIDE | | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 0 LU =0.00 EUR | 211.80 EUR | | 50 % | 211.80 EUR |

Others

RIM FRONT LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 5 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 5 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|-------|--------|--------|--------|---|---|---|---|----|
| 327.36 | 58.80 | 318.35 | 211.80 | 190.00 | 0 | 0 | 0 | 0 | 0 |
| 221.46 | 58.80 | 159.18 | 105.90 | 190.00 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 364.36 | 741.95 | 0 | 1106.31 |
| HOG: 0 | BG: 0 | | NA Deprec. 735.34 |
| | | | 0.00% |
| | | | TOTAL 735.34 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 08/09/2017 Hour : 10:46 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |