

www.vabfleetservices.be Date: 18/09/2017 1/4

CMJBQ1

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	142218 KM
File nr. :	1438389	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FMU747 / WAUZZZ8V6EA	038400 /	yr of constructionr :	/
E-File nr. :		First registration :	22/08/2013
VFS-nr. :		Color :	BLUE D
Make + Model :	AUDI / A3	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	CEGEDIM BELGIUM SA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A3 SB Attraction 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes				
Variant car:		Engine size:	1598				
Gear box :	Manueel	Number of places:	5				
Number of gears:	5	Number of doors:	5				
HP:	105	kW:	77				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:	No				
		Use:	Unknown				
General condition:							



www.vabfleetservices.be Date: 18/09/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

E			105					D		1.6	7.7	i I
	[x] Width		idth		Height			Туре		Rim	Index]
THE RESI	[,1]		-,,	OIL	,				,	Tructup .		
Wheel RES:	[x]		Tyre:	OK	/	Rim:			/	Hubcap:		
Wheel RR:	[x]	CONTINENTAL	Tyre:	OK	[x] 2-4/	Rim:			/	Hubcap:		
Wheel FR:	[x]	CONTINENTAL	Tyre: [x] OK	[x] 2-4/	Rim:			/	Hubcap:		
Wheel RL:	[x]	CONTINENTAL	Tyre:	OK	[x] 2-4/	Rim:	[x]	WHEEL SCRATCHED) /	Hubcap:		
Wheel FL:	[x]	CONTINENTAL	Tyre:	OK	[x] 2-4/	Rim:			/	Hubcap:		

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 18/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/RIGHT/CENTER DENT

[x] BONNET/CENTER/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE) POLIR

[x] FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

TIVE TRAD	ITIONAL	GENERAL		
	0	0		0
: 0	3G: 1		NA Deprec.	0
			0.00%	
			TOTAL	0



www.vabfleetservices.be Date: 18/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS			NORMAL CONCLU	JSION		
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min	
NOT EXECUTED : Reason :	: No	I		ı		
Remark :						
Prices in EUR v	without VAT					
Authorized by customer :			Executed by VAB Fleet Se	ervices		
Remark authorized	customer :					
Date :	18/09/2017	Hour: 15:23				
Company :						
Executed by VAB F Services	leet					
E-Mail:	@					
Signature authorized	by customer					