

www.vabfleetservices.be Date: 21/09/2017 1/4

CNU50E

[X] COLLECTION [X] EFFECTIVE [] NOT EXECUTED [] DELIVERY

[x] = Status Modification

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 91966 KM File nr. : Mileage start / arrival: 0 / 01439365 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FTV320 / WF0LXXGCBLDP32610 / E-File nr. : First registration: 23/10/2013 VFS-nr.: Color: **SILVER** Make + Model : Fuel type : FORD / FOCUS CLIPPER **DIESEL**

Object nr. : Fuel: 43641

No

Classification: **Environment Class:** EURO 5

Customer company: Co2: T-GROEP NV 88g/km

Driver : Remote controls:

TISSUE Covering: Number keys : 2[x]

Vehicle kind: Seats (minivan): 0

Vehicle type: FOCUS CLIP. ECOnetic Trend 88g 105PK Country registration: **BELGIUM**

BREAK 1560 Variant car: Engine size: Gear box : Number of places: Manueel 5 Number of gears: 6 Number of doors: 5 HP: 105 kW: 77 Fisc HP Imported vehicle: Animals transported: No Smoked in vehicle: No Due date vehicle inspection: Extra set of tires: No Use: Unknown

Metallic paint:

General condition:

VAT over the margin - car:



www.vabfleetservices.be Date: 21/09/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

		[x]	Width			He	ight		Type		Rim	Index
Wheel RES:	[x]		Tyre:		OK		/	Rim:		/	Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap: [x	s] SCRATCHED
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap: [x	s] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 21/09/2017 3/4

STATUS: NOT ACCEPTABLE

300	dywork '	& window	s								
x]	REAR DO	OR/LEFT/FRONT	Γ		DENT				OVER KARAKTERLIJN		
				Repair pain	t - LI	New paint - E	New paint - E			Total	
	1 0 LU =0.00) EUR		318.35 EUR				50 %		318.35 EUR	
x]	THRESHO	OLD FRONT/LEF	Γ/CENTER		OTHER DAMAGES			DEURRUBBER Unit price Depr.			
	Number Code			Description			Unit pri			Total	
	2 I 1	i-vab-ander-01		REPAIR (PE	ER 15')		18.74 E	EUR		18.74 EUR	
	1	2	3	4	5	6	7	8	9	10	
	318.35	18.74	0	0	0	0	0	0	0	0	
	159.18	18.74	0	0	0	0	0	0	0	0	
Г			ITIONAL		GENERAL						
			18.35		0						
	НОС	G: 0	В	G: 0			NA Dep	NA Deprec.			
		•			7		0.00%	6	1		

TOTAL

177.92



www.vabfleetservices.be Date: 21/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS			NORMAL CONCLUSION							
Extra Time :	0 min	Waiting time: 0 min Reason:	1	Towing time : Reason :	0 min					
NOT EXECUTED Reason:	: No	I		<u> </u>						
Remark :	'									
Prices in EUR	without VAT									
Authorized by customer:			Executed by VAB Fleet Se	ervices						
Remark authorized	d customer :									
Date :	21/09/2017	Hour: 10:38								
Company :										
Executed by VAB l Services	Fleet									
E-Mail:	@									
Signature authorized	d by customer		†							