

CMLO7V

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	138057 KM
File nr. :	1438449	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1BPB710 / WV1ZZZ7HZCH013928 /		yr of constructionr :	/
E-File nr. :		First registration :	25/07/2011
VFS-nr. :		Color :	WHITE
Make + Model :	VOLKSWAGEN / TRANSPORTER	Fuel type :	DIESEL
Object nr. :	205	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Jungheinrich nv	Co2:	190g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	TRANSP.1200 B/F SWB 84PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1968
Gear box :	Manueel	Number of places:	3
Number of gears:	5	Number of doors:	4
HP:	84	kW:	62
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	NOK [x] BROKEN DOWN / DAMAGED
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :	OK	[x]	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RES:	[x]	UNIROYAL	Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	65	R	16	T
Rear tyre	205	65	R	16	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/RIGHT/CENTER DENT

Accessories and others

[x] VEH COVERED WITH STICKERS STICKER(S)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR MUDGUARD/CENTER/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	193.71 EUR		50 %	193.71 EUR

[x] REAR MUDGUARD/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR

Interior

[x] BOOT LID IN HOLE

	Repair paint - LI	New paint - E	Depr.	Total
2 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

AUTORADIO

Number	Code	Description	Unit price	Depr.	Total	
1	A 1	a-vab-verva-14	REPLACE	80.00 EUR	50 %	80.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	BEKLEDING	20.00 EUR	50 %	20.00 EUR

1	2	3	4	5	6	7	8	9	10
80.00	44.00	231.15	193.71	0	0	0	0	0	0
40.00	22.00	115.58	96.86	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	468.86	80.00	548.86
HOG: 0	BG: 3		NA Deprec. 274.43
			0.00%
			TOTAL 274.43

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/09/2017 Hour : 11:53 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	