

www.vabfleetservices.be Date: 22/09/2017 1/4

CQZ2LJ

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner:		Mileage :	26286 KM
File nr. :	1441794	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1RDS677 / YV1DZARC1H20	94449 /	yr of constructionr :	/
E-File nr. :		First registration :	24/11/2016
VFS-nr. :		Color :	BLUE
Make + Model :	VOLVO / XC60	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel:	
Classification:		Environment Class:	EURO 6
Customer company :	ONBEKEND	Co2:	117g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan):	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1969
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			



www.vabfleetservices.be Date: 22/09/2017 2/4

Original registr. number :			Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELL	I Tyre:	OK	[x]	4-6 /	Rim:		/	Hubcap :	
Wheel RL:	[x]	PIRELL	I Tyre:	OK	[x]	>6/	Rim:		/	Hubcap:	
Wheel FR:	[x]	PIRELL	I Tyre: [x	OK	[x]	4-6 /	Rim:		/	Hubcap:	
Wheel RR:	[x]	PIRELL	I Tyre:	OK	[x]	>6 /	Rim:		/	Hubcap:	
Wheel RES:	[x]		Tyre:	OK		/	Rim:		/	Hubcap:	
		[x]	Width	1	Hei	ight		Туре		Rim	Index
Fron	t tyre		235			55		R		17	V
Real	tvre		235		6	55		R		17	V

Remark:

Wheels and tyres:

	V				
Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 22/09/2017 3/4

STATUS: NOT ACCEPTABLE

Others		

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		58.32 EUR

1	2	3	4	5	6	7	8	9	10
58.32	0	0	0	0	0	0	0	0	0
58.32	0	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
58.32		0	0	58.32
58.32	NA Deprec.		BG: 0	HOG: 0
,	0.00%			
58.32	TOTAL			



www.vabfleetservices.be Date: 22/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	STANCES		UNDER CONDITION - VEHICLE WET						
Extra Time :	0 min	Waiting time: 0 m Reason:	nin	Towing time : Reason :	0 min				
NOT EXECUTED Reason:	: No			I					
Remark :									
Prices in EUR	without VAT								
Authorized by customer:			Executed by VA	B Fleet Services					
Remark authorize	d customer :								
Date :	22/09/2017	Hour: 08:45							
Company : Executed by VAB Services	Fleet								
E-Mail:	@								
Signature authorize	d by customer								