

CQEJVF

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	86985 KM
File nr. :	1441328	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DWT777 / YV1BW31A0D1259477 /		yr of constructionr :	/
E-File nr. :		First registration :	20/09/2012
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / V70	Fuel type :	DIESEL
Object nr. :	54434	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Vesuvius Group sa	Co2:	149g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V70 D3 Kinetic St/St Geartr.136PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1984
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :		
Warning vest :				Transport licence :		
Tax certificate :				Navigation CD/SD/DVD		
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		Oil level :	OK	[x]
Jack, wheelspanner :				Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		225	50	R	17	W
Rear tyre		225	50	R	17	W

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

[x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/RIGHT/CORNER DENT

		Repair paint - LI	New paint - E	Depr.	Total
4	15 LU =72.00 EUR	0 EUR	282.96 EUR	50 %	354.96 EUR

[x] REAR MUDGUARD/LEFT/CENTER DENT

		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	369.84 EUR		50 %	369.84 EUR

[x] FRONT MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	264.21 EUR		50 %	264.21 EUR

[x] BONNET/CENTER/RIGHT OTHER DAMAGES INWERKING+ HAGEL

		Repair paint - LI	New paint - E	Depr.	Total
1	20 LU =96.00 EUR	348.09 EUR		50 %	444.09 EUR

[x] ROOF/CENTER/LEFT OTHER DAMAGES INWERKING

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	577.80 EUR		50 %	577.80 EUR

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1 REAR BUMPER		411.84 EUR	50 %	411.84 EUR

1	2	3	4	5	6	7	8	9	10
1021.89	264.21	369.84	766.80	95.00	0	0	0	0	0
510.94	132.10	184.92	383.40	95.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	2422.74	0	2517.74
HOG: 0	BG: 2		NA Deprec. 1306.37
			0.00%
			TOTAL 1306.37

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/09/2017 Hour : 12:39 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	