

CP3DPV

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	127428 KM
File nr. :	1440328	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FNF302 / WBA3K11060F854349 /		yr of constructionr :	/
E-File nr. :		First registration :	27/08/2013
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	714250	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CIPAL NV	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 TOURING 318dA 136PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	
Cert. of reg. / Part 1:		
Cert. of reg. copy / Part 2:	OK	[x]
Warning vest :	OK	[x]
Tax certificate :		
Fuel card :		
Mobile phone kit :		
First aid kit :	OK	[x]
Jack, wheelspanner :	OK	[x]
Service manual :		
Cert. of conformity :	OK	
Insurance certificate :		
Transport licence :		
Navigation CD/SD/DVD	OK	[x]
Car radio :	OK	[x]
Extinguisher :	OK	[x]
Warning triangle :	OK	[x]
Oil level :	OK	[x]
Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel RES:	[x]	MICHELIN	Tyre :	OK		/	Rim :		/	Hubcap :		

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	60	R	16	V
Rear tyre		205	60	R	16	V

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/REAR	DENT
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0
			0.00%
			TOTAL 0

APPRAISAL

www.vabfleetservices.be

Date : 22/09/2017

4/4

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min 	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 22/09/2017 Hour : 16:07	
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	
	