

CQ9TG8

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

|                               |                                |                          |                               |
|-------------------------------|--------------------------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING                | Cleanliness :            | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner :                       |                                | Mileage :                | 103937 KM                     |
| File nr. :                    | 1441231                        | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                                | Mileag ref. service :    | 0                             |
| 1DLK102 / WBA1C91040J198359 / |                                | yr of constructionr :    | /                             |
| E-File nr. :                  |                                | First registration :     | 15/06/2012                    |
| VFS-nr. :                     |                                | Color :                  | BROWN                         |
| Make + Model :                | BMW / 1 HATCH                  | Fuel type :              | DIESEL                        |
| Object nr. :                  | 5001                           | Fuel :                   |                               |
| Classification :              |                                | Environment Class:       | EURO 5                        |
| Customer company :            | INBEV BELGIUM SA               | Co2:                     | 99g/km                        |
| Driver :                      |                                | Remote controls:         | 2                             |
| Covering :                    | LEATHER                        | Number keys :            | 2 [x]                         |
| Vehicle kind :                | VEHICLE                        | Seats (minivan) :        | 0                             |
| Vehicle type :                | 1 HATCH 116d Eff.Dyn.Ed. 116PK | Country registration :   | BELGIUM                       |

|                              |         |                     |         |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car:   | No      | Metallic paint:     |         |
| Variant car:                 |         | Engine size:        | 1598    |
| Gear box :                   | Manueel | Number of places:   | 5       |
| Number of gears:             | 6       | Number of doors:    | 5       |
| HP:                          | 116     | kW:                 | 85      |
| Fisc HP                      |         | Imported vehicle:   |         |
| Animals transported:         |         | Smoked in vehicle:  |         |
| Due date vehicle inspection: |         | Extra set of tires: |         |
|                              |         | Use:                | Unknown |
| General condition:           |         |                     |         |

|                              |    |                       |                         |        |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number :   | OK | Service manual :      | OK                      | [x]    |
| Cert. of reg. / Part 1:      |    | Cert. of conformity : | OK                      |        |
| Cert. of reg. copy / Part 2: | OK | [x]                   | Insurance certificate : |        |
| Warning vest :               | OK | [x]                   | Transport licence :     |        |
| Tax certificate :            |    |                       | Navigation CD/SD/DVD    |        |
| Fuel card :                  |    |                       | Car radio :             | OK [x] |
| Mobile phone kit :           |    |                       | Extinguisher :          | OK [x] |
|                              |    |                       | Warning triangle :      | OK [x] |
| First aid kit :              | OK | [x]                   | Oil level :             | OK [x] |
| Jack, wheelspanner :         |    |                       | Filled up :             | 0      |

## Wheels and tyres: Summer tires

|            |     |          |        |     |     |       |       |       |                 |                            |
|------------|-----|----------|--------|-----|-----|-------|-------|-------|-----------------|----------------------------|
| Wheel FL:  | [x] | MICHELIN | Tyre : | OK  | [x] | 4-6 / | Rim : |       | /               | Hubcap :                   |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK  | [x] | 4-6 / | Rim : | [x]   | WHEEL SCRATCHED | / Hubcap :                 |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK  | [x]   | 4-6 / | Rim : | [x]             | WHEEL SCRATCHED / Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK  | [x] | 4-6 / | Rim : |       | /               | Hubcap :                   |
| Wheel RES: | [x] |          | Tyre : | OK  |     | /     | Rim : |       | /               | Hubcap :                   |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205   | 55     | R    | 16  | V     |
| Rear tyre  | 205   | 55     | R    | 16  | V     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |  |   |          |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

|     |                          |                           |
|-----|--------------------------|---------------------------|
| [x] | FRONT DOOR/LEFT/REAR     | SCRATCH WITH PAINT DAMAGE |
| [x] | WINDSCREEN/CENTER/LEFT   | CHIPS                     |
| [x] | FRONT DOOR/RIGHT/REAR    | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT BUMPER/CENTER/LEFT | CHIPS                     |

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                          |                   |               |            |
|-----|--------------------------|-------------------|---------------|------------|
| [x] | REAR BUMPER/CENTER/RIGHT | DENT              |               |            |
|     |                          | Repair paint - LI | New paint - E | Depr.      |
|     |                          |                   |               | Total      |
| 2   | 5 LU =24.00 EUR          | 254.16 EUR        | 50 %          | 278.16 EUR |

### Others

RIM REAR LEFT

| Number | Code                  | Description        | Unit price | Depr. | Total     |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 3      | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code                  | Description        | Unit price | Depr. | Total     |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 3      | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

| 1 | 2      | 3      | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|---|--------|--------|---|---|---|---|---|---|----|
| 0 | 278.16 | 190.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| 0 | 139.08 | 190.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                   |
|------------|-------------|---------|-------------------|
| 190.00     | 278.16      | 0       | 468.16            |
| HOG: 0     | BG: 2       |         | NA Deprec. 329.08 |
|            |             |         | 0.00%             |
|            |             |         | TOTAL 329.08      |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                               |                                  |                                 |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min            | Waiting time : 0 min<br>Reason : | Towing time : 0 min<br>Reason : |
| NOT EXECUTED : No<br>Reason : |                                  |                                 |
| Remark :                      |                                  |                                 |

## Prices in EUR without VAT

|                                                                                                                                                                      |                                |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| Authorized by customer :<br><br>Remark authorized customer :<br><br>Date : 25/09/2017      Hour : 14:23<br>Company :<br>Executed by VAB Fleet Services<br>E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br><br>                                           |                                |