

CQW105

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	178167 KM
File nr. :	1441740	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CTN197 / WBA3D31010F301467 /		yr of constructionr :	/
E-File nr. :		First registration :	24/02/2012
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	5711	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SBB BEDRIJFSDIENSTEN BV-CVBA	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 BER 320d 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork l& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork l& windows

[x]	REAR DOOR/RIGHT/FRONT			OTHER DAMAGES		SLECHT HERSTELD	
	Number	Code	Description	Unit price	Depr.	Total	
0	0						
[x]	FRONT DOOR/LEFT/FRONT			DENT			
	Number	Code	Description	Unit price	Depr.	Total	
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR	
[x]	WINDSCREEN/CENTER/RIGHT			WINDOW DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total	
2	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR	
	Number	Code	Description	Unit price	Depr.	Total	
2	I 1	i-vab-herstr-02	SUPPL WINDOW REPAIR	29.40 EUR		29.40 EUR	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4 personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR		45.88 EUR

1	2	3	4	5	6	7	8	9	10
45.88	88.20	63.00	0	0	0	0	0	0	0
45.88	88.20	63.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
197.08	0	0	197.08
HOG: 0	BG: 0		NA Deprec. 197.08
			0.00%
			TOTAL 197.08

APPRAISAL

www.vabfleetservices.be

Date : 28/09/2017

6/6

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 28/09/2017 Hour : 11:45	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	