

www.vabfleetservices.be Date: 25/09/2017 1/5

CPT7EE

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar: KBC REMARKETING Cleanliness: INT: CLEAN [x] EXT: CLEAN [x]

Owner: Mileage: 115829 KM

File nr.: 1440882 Mileage start / arrival: 0 / 0

Reg number / Chassis / Ref:

1FGV959 / WDD2040001G149610 /

yr of construction: /

E-File nr.: First registration: 25/06/2013

VFS-nr.: Color: GREY

Make + Model : MERCEDES / C Fuel type : DIESEL

Object nr.: 43279 Fuel:

Classification: Environment Class: EURO 5

Customer company: BELGACOM INS/FLEET NV Co2: 127g/km

Driver: Remote controls: 2

Covering: PARTIAL LEATHER Number keys: 2 [x]

Vehicle kind : VEHICLE Seats (minivan) : ()

Vehicle type: C BER 180 CDI BlueEFF. S&S 120PK Country registration: BELGIUM

VAT over the margin - car: No Metallic paint: Yes

Variant car:BERLINEEngine size:2143

Gear box: Manueel Number of places: 5

Number of gears: 6 Number of doors: 4

HP: 120 kW: 88

Fisc HP Imported vehicle:

Animals transported: Smoked in vehicle:

Due date vehicle inspection: Extra set of tires:

Use: Unknown

General condition:



www.vabfleetservices.be Date: 25/09/2017 2/5

Original registr. number : OK Service manual : OK Cert. of conformity: Cert. of reg. / Part 1: NOK MISSING/INCOMPLETE OK Insurance certificate: OK Cert. of reg. copy / Part 2: Transport licence: Warning vest: OK Tax certificate: Navigation CD/SD/DVD Fuel card : OK Car radio: OK Mobile phone kit : Extinguisher: OK Warning triangle: OK Oil level: OK First aid kit: OK Filled up: 0 Jack, wheelspanner :

Wheels and tyres: Summer tires

Wheel FL:	HANGKOOK	Tyre:	OK	>6 /	Rim:		/ Hubcap:
Wheel RL:	PIRELLI	Tyre:	OK	2-4 /	Rim:		/ Hubcap:
Wheel FR:	HANGKOOK	Tyre:	OK	>6 /	Rim:	WHEEL SCRATCHED	/ Hubcap:
Wheel RR:	PIRELLI	Tyre:	OK	2-4 /	Rim:		/ Hubcap:
Wheel RES:	HANGKOOK	Tyre:	OK	/	Rim:		/ Hubcap:

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Type	Rim	Index
Front tyre	0	0		0	
Rear tyre	0	0		0	

Remark:



Date: 25/09/2017 www.vabfleetservices.be 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

Boo	dywork \& windows		
[x]	REAR DOOR/CENTER/LEFT	DENT	
[x]	REAR DOOR/LEFT/CENTER	DENT	
[x]	ROOF/CENTER/LEFT	OTHER DAMAGES	HERSTELD OVB
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/RIGHT/CENTER	DENT	
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/RIGHT/REAR	DENT	
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE	
Inte	rior		

[x]

SEAT FL OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

WINDS	CREEN/CENTER/LEFT	WINDOW DAMAGE		2X	
Numbe	r Code	Description	Unit price	Depr.	Total
1 I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
Numbe	r Code	Description	Unit price	Depr.	Total
1 I 1	i-vab-herstr-02	SUPPL WINDOW REPAIR	29.40 EUR		29.40 EUR

1	2	3	4	5	6	7	8	9	10
88.20	0	0	0	0	0	0	0	0	0
88.20	0	0	0	0	0	0	0	0	0



www.vabfleetservices.be Date: 25/09/2017 4/5

		GENERAL	TRADITIONAL	INNOVATIVE
88.20		0	0	88.20
88.20	NA Deprec.		BG: 0	HOG: 0
	0.00%			
88.20	TOTAL			



www.vabfleetservices.be Date: 25/09/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

NORMAL CONCLUSION

				NORMAL CONCLUSION				
Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min			
		Reason:		Reason:				
NOT EXECUTED :	No	•		•				
Reason :								
Remark:	POLITIEATTE	ST AANWEZIG GVA						
Prices in EUR w	vithout VAT							
Authorized by customer :			Executed by	VAB Fleet Services				
Remark authorized	customer :							
Date :	25/09/2017	Hour:						
Company :								
Executed by VAB Fl Services	leet							
E-Mail :	@							
Signature authorized	by customer							
×								