

www.vabfleetservices.be Date: 25/09/2017 1/5

CPH7PR

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Variant car:

No

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 162950 KM File nr. : Mileage start / arrival: 0 / 01440652 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FRP569 / WDD2462121J186900 / E-File nr. : First registration: 10/03/2013 VFS-nr.: Color: **BEIGE** Make + Model : Fuel type : MERCEDES / B **DIESEL** Object nr. : Fuel: 74419 **Environment Class:** Classification: EURO 5 Customer company: Co2: **BRUSSELS AIRPORT COMPANY** 108g/km NV Driver: Remote controls: 2 Covering: LEATHER Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): Vehicle type: B 180 CDI BE 109PK Country registration: **BELGIUM**

Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:		1	

Metallic paint: Engine size:

1461



www.vabfleetservices.be Date: 25/09/2017 2/5

Original registr. number :	OK		Service manual :		
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

		[x]	Width		He	ight			Туре	Rim	Index
Wheel RES:	[x]		Tyre:	OK		/	Rim:			/ Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	K] OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:	
Wheel RL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHEE	Hubcap:	
Wheel FL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	Н
Rear tyre	205	55	R	16	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



Date: 25/09/2017 www.vabfleetservices.be 3/5

Во	dywork \& windows					
[x]	REAR BUMPER/CENTER/LEFT		SCRATCH (WITHOUT	PAINT DAMAGE)	
x]	REAR MUDGUARD/RIGHT/FRONT		DENT			
x]	REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAIN	T DAMAGE		
x]	FRONT MUDGUARD/RIGHT/CENTER		SCRATCH (WITHOUT	PAINT DAMAGE)	
nte	erior					
[x]	BOOT LID IN		CARVED			
Ac	cessories and others					
[x]	SIDE PROTECTION		OTHER DAMAGES			
	SIDE TROTLE HOLV		OTHER DAMAGES			
	ATUS: NOT ACCEPTA	BLE	OTHER DAMAGES			
ST		BLE	OTHER DAMAGES			
ST Bo	ATUS: NOT ACCEPTA	BLE	DENT		X2	
ST Bo	ATUS: NOT ACCEPTA	BLE Description		Unit price	X2 Depr.	Total
ST Bo	ATUS: NOT ACCEPTA dywork \& windows REAR DOOR/LEFT/FRONT			Unit price 63.00 EUR		Total 63.00 EUR
ST Bo	ATUS: NOT ACCEPTA dywork \& windows REAR DOOR/LEFT/FRONT Number Code	Description		_		
ST Bo	ATUS: NOT ACCEPTA dywork \& windows REAR DOOR/LEFT/FRONT Number Code 3 I 1 i-vab-uitd-01	Description BEAT OUT DENT	DENT	63.00 EUR	Depr.	63.00 EUR
ST	ATUS: NOT ACCEPTA dywork \& windows REAR DOOR/LEFT/FRONT Number Code 3 I 1 i-vab-uitd-01 Number Code	Description BEAT OUT DENT Description	DENT	63.00 EUR Unit price	Depr.	63.00 EUR Total 19.80 EUR
ST Bo	ATUS: NOT ACCEPTA dywork \& windows REAR DOOR/LEFT/FRONT Number Code 3 I 1 i-vab-uitd-01 Number Code 3 I 1 i-vab-uitd-02	Description BEAT OUT DENT Description	DENT PPL	63.00 EUR Unit price	Depr.	63.00 EUR Total 19.80 EUR
Bo [x]	ATUS: NOT ACCEPTA dywork \& windows REAR DOOR/LEFT/FRONT Number Code 3 I 1 i-vab-uitd-01 Number Code 3 I 1 i-vab-uitd-02	Description BEAT OUT DENT Description BEAT OUT DENT SU	DENT PPL OTHER DAMAGES	63.00 EUR Unit price	Depr. CHEMISCHE II	63.00 EUR Total 19.80 EUR NSLAG
Bo [x]	ATUS: NOT ACCEPTA dywork \& windows REAR DOOR/LEFT/FRONT Number Code 3 I 1 i-vab-uitd-01 Number Code 3 I 1 i-vab-uitd-02 ROOF/REAR/RIGHT	Description BEAT OUT DENT Description BEAT OUT DENT SU Repair paint - LI	DENT PPL OTHER DAMAGES	63.00 EUR Unit price	Depr. CHEMISCHE II Depr.	63.00 EUR Total 19.80 EUR NSLAG Total

Others

2 I 1

RIM	REAR	LEFT

i-vab-herstr-01

N	umber	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	·	95.00 EUR

58.80 EUR

58.80 EUR

WINDOW REPAIR



www.vabfleetservices.be Date: 25/09/2017 4/5

1	2	3	4	5	6	7	8	9	10
0	58.80	82.80	481.50	95.00	0	0	0	0	0
0	58.80	82.80	240.75	95.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
236.60	481.50	0		718.10
HOG: 0	BG: 0		NA Deprec.	477.35
			0.00%	
			TOTAL	477.35



www.vabfleetservices.be Date: 25/09/2017 5/5

[x] = Status Modification

Pictures: No

rictures: No					
CIRCUMS	TANCES		NORMAL CONCLU	JSION	
Extra Time :	0 min	Waiting time: 0 mi Reason:	in	Towing time : Reason :	0 min
NOT EXECUTED	: No			<u> </u>	
Reason:					
Remark:					
Prices in EUR	without VAT				
Authorized by customer:			Executed by VAB Fleet Se	ervices	
Remark authorized	l customer :				
Date :	25/09/2017	Hour: 11:40			
Company : Executed by VAB I Services	Fleet				
E-Mail :	@				
Signature authorized	by customer		+		