

CQCKKV

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	144660 KM
File nr. :	1441282	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ASU892 / VF1JZ1GB645048899 /		yr of constructionr :	/
E-File nr. :		First registration :	17/03/2011
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :	51354	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	RELAITRON SA	Co2:	128g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.SCENIC Dynamique 7pl. FAP 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1461
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :		
Warning vest :	OK	[x]		Transport licence :		
Tax certificate :				Navigation CD/SD/DVD	OK	[x]
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		Oil level :	OK	[x]
Jack, wheelspanner :				Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/ Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	60	R	16	H
Rear tyre		205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN
[x]	REAR BUMPER/SIDE/LEFTCENTER	SCRATCH WITH PAINT DAMAGE	

Interior

[x]	SEAT FL	OTHER DAMAGES
-----	---------	---------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/RIGHT		OTHER DAMAGES		SLECHTE HERSTELLING	
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	REAR WINDOW/LEFT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
3	0	LU =0.00 EUR	0 EUR		50 %	
			Repair paint - LI	New paint - E	Depr.	Total
3	25	LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	ROOF/REAR/RIGHT		DENT		MEERDERE	
			Repair paint - LI	New paint - E	Depr.	Total
6	0	LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR
[x]	REAR DOOR/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		+DEUKEN	
			Repair paint - LI	New paint - E	Depr.	Total
4	0	LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		+DEUKEN	
			Repair paint - LI	New paint - E	Depr.	Total
5	0	LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
1	0	LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] FRONT BUMPER/RIGHT/SIDE

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
431.98	110.64	370.00	318.35	318.35	481.50	0	0	0	0
215.99	110.64	185.00	159.18	159.18	240.75	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
110.64	1920.18	0	2030.82
HOG: 0	BG: 0		NA Deprec. 1070.73
			0.00%
			TOTAL 1070.73

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 22/09/2017 Hour : 13:51 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	