

www.vabfleetservices.be Date: 06/10/2017 1/4

CVSHTF

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Vehicle type:

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 107173 KM File nr. : Mileage start / arrival: 0 / 01445583 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DOH109 / WVWZZZ3CZCP046337 / E-File nr. : First registration: 05/07/2012 Color: VFS-nr.: **BROWN** Make + Model : Fuel type : VOLKSWAGEN / PASSAT **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: **KBC BANK NV** 114g/km Driver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0

Country registration:

BELGIUM

PASSAT BER Comfortline BMT 105PK

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		I	



Date: 06/10/2017 www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wh	eel FL:	[x]	CON	TINENTAL	Tyre:		OK	[x]	4-6 /	Rim:			/	Hubcap :	
Wh	eel RL :	[x]	BRII	DGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:	
Wh	eel FR:	[x]	CON	NTINENTAL	Tyre:	[x]	OK	[x]	4-6 /	Rim:			/	Hubcap:	
Wh	eel RR :	[x]	BRII	DGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:	
Wh	eel RES:	[x]	ANI	DERE	Tyre:		OK	[x]	>6/	Rim:			/	Hubcap:	
l			[x]	W	idth			He	ight			Type		Rim	Index
	Fron	t tyre		2	215			5	55			R		16	W

 F3		8	- J P -		
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap :
1					

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 06/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT MUDGUARD/LEFT/FRONT

SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT DOOR/LEFT/REAR

SCRATCH WITH PAINT DAMAGE

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

1	2	3	4	5	6	7	8	9	10
115.56	0	0	0	0	0	0	0	0	0
115.56	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
115.56	0	0		115.56
HOG: 0	BG: 0		NA Deprec.	115.56
			0.00%	

TOTAL 115.56



www.vabfleetservices.be Date: 06/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS			NORMAL CONCLU	JSION	
Extra Time :	0 min	Waiting time: 0 min Reason:	1	Towing time : Reason :	0 min
NOT EXECUTED Reason:	: No	I			
Remark:					
Prices in EUR	without VAT				
Authorized by customer:			Executed by VAB Fleet So	ervices	
Remark authorized	l customer :				
Date :	06/10/2017	Hour: 09:56			
Company :					
Executed by VAB I Services	Fleet				
E-Mail :	@				
Signature authorized	l by customer				