

CV6QXW

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------|----------------------------------|--------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 140643 KM |
| File nr. : | 1445107 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FPE660 / WVWZZZ3CZEE043186 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 12/09/2013 |
| VFS-nr. : | | Color : | BROWN |
| Make + Model : | VOLKSWAGEN / PASSAT BREAK | Fuel type : | DIESEL |
| Object nr. : | 63793 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | BIOCARTIS NV | Co2: | 116g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | PASSAT VAR Comfortline BMT 105PK | Country registration : | BELGIUM |

| | | | |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1598 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 105 | kW: | 77 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

| | |
|--------------------|--|
| General condition: | |
|--------------------|--|

| | | | | | |
|-------------------------------------|----|-----|--------------------------------|----|-----|
| Original registr. number : | OK | | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | | | Insurance certificate : | | |
| Warning vest : | OK | [x] | Transport licence : | | |
| Tax certificate : | | | Navigation CD/SD/DVD | OK | [x] |
| Fuel card : | | | Car radio : | OK | [x] |
| Mobile phone kit : | | | Extinguisher : | OK | [x] |
| | | | Warning triangle : | OK | [x] |
| First aid kit : | OK | [x] | Oil level : | OK | [x] |
| Jack, wheelspanner : | OK | [x] | Filled up : | 0 | |

Wheels and tyres: Summer tires

| | | | | | | | | | | | | |
|-------------------|-----|----------|---------------|-----|-----|-------|--------------|--------------|---|-----------------|-----------------|--|
| Wheel FL : | [x] | GOODYEAR | Tyre : | OK | [x] | 2-4 / | Rim : | | / | Hubcap : | | |
| Wheel RL : | [x] | GOODYEAR | Tyre : | OK | [x] | 2-4 / | Rim : | | / | Hubcap : | | |
| Wheel FR : | [x] | GOODYEAR | Tyre : | [x] | OK | [x] | 2-4 / | Rim : | | / | Hubcap : | |
| Wheel RR : | [x] | GOODYEAR | Tyre : | OK | [x] | 2-4 / | Rim : | | / | Hubcap : | | |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | | / | Hubcap : | | |

| | | | | | | |
|-------------------|-----|--------------|---------------|-------------|------------|--------------|
| | [x] | Width | Height | Type | Rim | Index |
| Front tyre | | 215 | 55 | R | 16 | W |
| Rear tyre | | 215 | 55 | R | 16 | W |

Remark :

Wheels and tyres:

| | | | | | | |
|------------|--------|----|---|-------|---|----------|
| Wheel FL: | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | Tyre : | OK | / | Rim : | / | Hubcap : |

| | | | | | |
|------------|-------|--------|------|-----|-------|
| [x] | Width | Height | Type | Rim | Index |
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|-------------------------|--------------------------------|
| [x] | REAR BUMPER/LEFT/LEFT | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | REAR BUMPER/RIGHT/RIGHT | SCRATCH WITH PAINT DAMAGE |
| [x] | WINDSCREEN/CENTER/LEFT | CHIPS |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | |
|-----|------------------------------|---------------------------|
| [x] | REAR DOOR/RIGHT/CORNER/BELOW | SCRATCH WITH PAINT DAMAGE |
|-----|------------------------------|---------------------------|

| | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|------------|
| 2 0 LU =0.00 EUR | 318.35 EUR | | 50 % | 318.35 EUR |

| | | |
|-----|-------------------------|---------------|
| [x] | FRONT BUMPER/RIGHT/SIDE | OTHER DAMAGES |
|-----|-------------------------|---------------|

| Number | Code | Description | Unit price | Depr. | Total |
|--------|--------------------|------------------|------------|-------|-----------|
| 1 | I 1 i-vab-ander-01 | REPAIR (PER 15') | 18.74 EUR | | 18.74 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|--------|---|---|---|---|---|---|---|----|
| 18.74 | 318.35 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 18.74 | 159.18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|-------------------|
| 18.74 | 318.35 | 0 | 337.09 |
| HOG: 0 | BG: 0 | | NA Deprec. 177.92 |
| | | | 0.00% |
| | | | TOTAL 177.92 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|--|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 11/10/2017 Hour : 11:47 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |