

CUTQCI

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	26712 KM
File nr. :	1444820	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1RFV877 / WVWZZZ3CZHE115311 /		yr of constructionr :	/
E-File nr. :		First registration :	13/12/2016
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / PASSAT BREAK	Fuel type :	DIESEL
Object nr. :	57617	Fuel :	
Classification :	C	Environment Class:	EURO 5
Customer company :	UNIVERSITAIR ZIEKENHUIS BRUSSEL	Co2:	110g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:		Engine size:	1968
Gear box :	Manueel	Number of places:	
Number of gears:	6	Number of doors:	
HP:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :		[x]	Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :		

	[x]	Width	Height	Type	Rim	Index
Front tyre		215	55	R	17	V
Rear tyre		215	55	R	17	V

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR DOOR/CENTER/RIGHT DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	301.68	0	0	0	0	0	0	0	0
105.90	150.84	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	513.48	0	513.48
HOG: 0	BG: 0		NA Deprec. 256.74
			0.00%
			TOTAL 256.74

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/10/2017 Hour : 09:14 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	