

www.vabfleetservices.be Date: 13/10/2017 1/4

CXIXDQ

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 138807 KM File nr. : Mileage start / arrival: 1446906 0 / 0Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1ENW750 / WAUZZZ8T2DA045776 / E-File nr. : First registration: 04/02/2013 Color: VFS-nr.: **BROWN** Make + Model : Fuel type : AUDI / A5 SPORTBACK **DIESEL** Object nr. : Fuel: 54622 **Environment Class:** Classification: EURO 5 Customer company: Co2: Ceva Logistics Belgium nv 127g/km Driver : Remote controls: LEATHER Covering: Number keys: 1 [x] Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: A5 SB DPF Multitr.163PK Aut. Country registration: **BELGIUM**

Variant car:		Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
нр:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 13/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

							_		
		[x]	Width		Height		Туре	Rim	Index
Wheel RES:	[x]		Tyre :	OK	/	Rim:		/ Hubcap :	
Wilse I DEC.	r1		Т	OV	,	D!		/ II	
Wheel RR:	[x]	GOODYEAR	Tyre:	OK	[x] 2-4/	Rim:		/ Hubcap:	
Wheel FR:	[x]	GOODYEAR	Tyre: [x]	OK.	[x] 2-4/	Rim:		/ Hubcap:	
Wheel RL:	[x]	GOODYEAR	Tyre:	OK	[x] 2-4/	Rim:		/ Hubcap:	
Wheel FL:	[x]	GOODYEAR	Tyre:	OK	[x] 2-4/	Rim:		/ Hubcap:	

	x] Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	V
Rear tyre	225	50	R	17	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 13/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Interior

[x] SEAT REAR L OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[X] FRONT MUDGUARD/RIGHT/CENTER OTHER DAMAGES SLECHTE HERSTELLING

Number Code Description Unit price Depr. Total

0 0

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 2		NA Deprec.	0
			0.00%	
			TOTAL	0



13/10/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No)								
CIRCUMS	TANCES		NORMAL CONCLUSION						
Extra Time :	0 min	Waiting time : Reason :	0 min	Towing time : Reason :	0 min				
NOT EXECUTED :	: No	I		I					
Remark:									
Prices in EUR v	without VAT								
Authorized by customer :			Executed by VAB F	leet Services					
Remark authorized	customer :								
Date : Company :	13/10/2017	Hour: 12:03							
Executed by VAB F Services	Fleet .								
E-Mail :	@								
Signature authorized	by customer								