

D10D8C

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	131099 KM
File nr. :	1449600	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GKD078 / WF0MXXGBWMDK77652 /		yr of constructionr :	/
E-File nr. :		First registration :	28/02/2014
VFS-nr. :		Color :	BLACK
Make + Model :	FORD / GALAXY	Fuel type :	DIESEL
Object nr. :	714250	Fuel :	
Classification :	I	Environment Class:	EURO 5
Customer company :	CIPAL SCHAUBROECK NV	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1997
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :		

	[x]	Width	Height	Type	Rim	Index
Front tyre		225	50	R	17	V
Rear tyre		225	50	R	17	V

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	DENT
[x]	FRONT DOOR/RIGHT/REAR	DENT
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	362.02 EUR		50 %	362.02 EUR

Interior

[x]	LUGGAGE COVER	MISSING/INCOMPLETE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	0 EUR		50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	LUGGAGE COVER	288.00 EUR	50 %	288.00 EUR

1	2	3	4	5	6	7	8	9	10
362.02	288.00	0	0	0	0	0	0	0	0
181.01	144.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	650.02	0	650.02
HOG: 0	BG: 2		NA Deprec. 325.01
			0.00%
			TOTAL 325.01

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/10/2017 Hour : 12:46 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	