

CSQBPL

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	108667 KM
File nr. :	1443163	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FMB386 / VF1JZ14P649399317 /		yr of constructionr :	/
E-File nr. :		First registration :	13/08/2013
VFS-nr. :		Color :	BLACK
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ON SEMICONDUCTOR BELGIUM BVBA	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GRAND SCENIC Expression 7pl.110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	MONOVOLUME	Engine size:	1461
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
		Warning triangle :	OK [x]
First aid kit :	OK [x]	Oil level :	OK [x]
Jack, wheelspanner :	OK [x]	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK [x]	2-4 /	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK [x]	2-4 /	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK [x]	2-4 /	Rim :	/	Hubcap :	[x] BROKEN / CRACKED
Wheel RR :	[x]	MICHELIN	Tyre :	OK [x]	2-4 /	Rim :	/	Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK [x]	4-6 /	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT THRESHOLD/RIGHT/CENTER	DENT	DEURINSLAG

STATUS: NOT ACCEPTABLE

Others

HUB CAP FR

Repair paint - LI

New paint - E

Depr.

Total

1 0 LU =0.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR		30.00 EUR

1	2	3	4	5	6	7	8	9	10
30.00	0	0	0	0	0	0	0	0	0
30.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	30.00	0	30.00
HOG: 0	BG: 0		NA Deprec. 30.00
			0.00%
			TOTAL 30.00

APPRAISAL

www.vabfleetservices.be

Date : 29/09/2017

4/4

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 29/09/2017 Hour : 13:06	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	