

D21IPW

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	92081 KM
File nr. :	1450420	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EBH627 / WAUZZZ8K9DA135708 /		yr of constructionr :	/
E-File nr. :		First registration :	10/10/2012
VFS-nr. :		Color :	BLACK
Make + Model :	AUDI / A4 AVANT	Fuel type :	DIESEL
Object nr. :	6079	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	COMPASS GROUP NV	Co2:	129g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	>6 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :		/ Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	>6 /	Rim :		/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	16	W
Rear tyre	225	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE	+DEUK		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
4	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT BUMPER/RIGHT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 5	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	72.90 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
72.90	211.80	211.80	370.00	0	0	0	0	0	0
72.90	105.90	105.90	185.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
72.90	793.60	0	866.50
HOG: 0	BG: 0		NA Deprec. 469.70
			0.00%
			TOTAL 469.70

APPRAISAL

www.vabfleetservices.be

Date : 24/10/2017

4/4

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 24/10/2017 Hour : 07:51	
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	
	