

www.vabfleetservices.be Date: 23/10/2017 1/5

D1PSJ2

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	113894 KM
File nr. :	1450137	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FUJ001 / WAUZZZ8R1EA04	42969 /	yr of constructionr :	/
E-File nr. :		First registration :	28/10/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / Q5	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	SECURITAS DIRECT NV	Co2:	159g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	Q5 S-tronic 163PK Aut.	Country registration :	BELGIUM

Variant car:	SUV	Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	

Metallic paint:

Yes



www.vabfleetservices.be Date: 23/10/2017 2/5

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Varning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
uel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
		Warning triangle :	OK
First aid kit :	OK	Oil level :	OK
ack, wheelspanner :		Filled up :	0

Wheels and tyres: Summer tires

	[v] Wi	idth		77	ight			Type	Dim	Indov
Wheel RES: [x]	VREDESTEIN	Tyre:	OK		/	Rim:			Hubcap:	
Wheel RR:	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:	
Wheel FR:	MICHELIN	Tyre: [x]	OK	[x]	1.6-2 /	Rim:			Hubcap: [2	x] MISSING/INCOMPLETE
Wheel RL:	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:			Hubcap:	
Wheel FL:	MICHELIN	Tyre:	OK	[x]	1.6-2 /	Rim:			Hubcap:	

[x] Width		Height	Type	Rim	Index	
Front tyre	235	65	R	17	W	
Rear tyre	235	65	R	17	W	

Remark: +COMPRESSEUR

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



I 1

i-vab-sp-01

APPRAISAL

23/10/2017 Date: www.vabfleetservices.be 3/5

ST	ATUS: ACCEPTABLE / I	JSAGE DAMA	GE				
Во	dywork \& windows						
[x]	REAR DOOR/CENTER/LEFT	STICKER(S)	STICKER(S)				
[x]	REAR MUDGUARD/RIGHT/CENTER		SCRATCH (WITHOUT	`PAINT DAMAGE	Ξ)		
[x]	REAR DOOR/LEFT/REAR		SCRATCH WITH PAIN	NT DAMAGE			
x]	REAR DOOR/RIGHT/FRONT		SCRATCH WITH PAIN	NT DAMAGE	POLIR		
x]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAIN	NT DAMAGE			
x]	FRONT DOOR/RIGHT/REAR		DENT				
[x]	BONNET/CENTER/LEFT		SCRATCH (WITHOUT	PAINT DAMAGE	Ε)		
[x]	FRONT MUDGUARD/RIGHT/CENTER		SCRATCH WITH PAIN	NT DAMAGE			
[x]	FRONT MUDGUARD/RIGHT/FRONT		SCRATCH (WITHOUT	PAINT DAMAGE	E)		
x]	BONNET/CENTER/LEFT/FRONT		CHIPS		L/R		
nte	erior						
x]	DOOR IN FL		CARVED				
x]	BOOT LID IN		SCRATCHED				
ST	ATUS: NOT ACCEPTAB	LE					
Во	dywork \& windows						
x]	REAR BUMPER/RIGHT/RIGHT		DENT				
		Repair paint - LI	New paint - E		Depr.	Total	
	2 0 LU =0.00 EUR	254.16 EUR			50 %	254.16 EUR	
x]	FRONT/LEFT		OTHER DAMAGES		LAK AF		
	Number Code	Description		Unit price	Depr.	Total	
	0						
x]	FRONT BUMPER/RIGHT		DENT				
	Number Code	Description		Unit price	Depr.	Total	

SPOTREPAIR

115.56 EUR

115.56 EUR



www.vabfleetservices.be Date: 23/10/2017 4/5

Others

HUB CAP FR

 Repair paint - LI
 New paint - E
 Depr.
 Total

 3 0 LU = 0.00 EUR
 50 %

_.

Pie	ces				
	Number Code	Description	Unit price	Depr.	Total

3 1 WHEEL CAP 36.00 EUR 50 % 36.00 EUR

1	2	3	4	5	6	7	8	9	10
115.56	254.16	36.00	0	0	0	0	0	0	0
115.56	127.08	18.00	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
405.72	0	290.16	115.56
NA Deprec. 260.64		BG: 2	HOG: 0

0.00%

TOTAL 260.64



www.vabfleetservices.be Date: 23/10/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS			NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min			
NOT EXECUTED Reason:	: No							
Remark :								
Prices in EUR	without VAT							
Authorized by customer :			Executed by VAB Fleet	Services				
Remark authorized	l customer :							
Date :	23/10/2017	Hour: 13:53						
Company :	Fleet							
Executed by VAB I Services E-Mail :	@							
Signature authorized	1 by customer							