

CY9X2C

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	56992 KM
File nr. :	1447480	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
HL8304 / WBAXX110400R35503 /		yr of constructionr :	2015 / 10
E-File nr. :		First registration :	16/10/2015
VFS-nr. :		Color :	BLUE D
Make + Model :	BMW / X4	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	PWC	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	190	kW:	140
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	17	V
Rear tyre	225	60	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT
[x]	REAR DOOR/RIGHT/FRONT	DENT
[x]	FRONT MUDGUARD/LEFT/REAR	DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/RIGHT/REAR	DENT
-----	-----------------------	------

Number	Code	Description	Unit price	Depr.	Total
0	0				

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 2		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 09:47 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	