

D6174A

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	129161 KM
File nr. :	1453581	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ECU617 / WVWZZZ3CZDE058907 /		yr of constructionr :	/
E-File nr. :		First registration :	23/10/2012
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / PASSAT BREAK	Fuel type :	DIESEL
Object nr. :	9837	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CEGEKA GROEP NV	Co2:	113g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PASSAT VAR Trendline BM 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	[x]
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
		Warning triangle :	OK
First aid kit :	OK	Oil level :	OK
Jack, wheelspanner :		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	2-4 /	Rim :	/	Hubcap :	
Wheel RL :	MICHELIN	Tyre :	OK	2-4 /	Rim :	/	Hubcap :	
Wheel FR :	MICHELIN	Tyre :	OK	2-4 /	Rim :	/	Hubcap :	
Wheel RR :	MICHELIN	Tyre :	OK	2-4 /	Rim :	/	Hubcap :	SCRATCHED
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	POLIR/RETOUCHE
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT	
[x]	REAR DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	BOORD DEUR
[x]	REAR DOOR/LEFT/FRONT	DENT	
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	BOORD DEUR
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	POLIR
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	BOORD DEUR
[x]	FRONT DOOR/LEFT/CENTER	DENT	
[x]	FRONT DOOR/RIGHT/CENTER	DENT	
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	

Interior

BOOT LID IN	SCRATCHED
-------------	-----------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT			DENT		
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	BONNET/CENTER/LEFT/FRONT			SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		290.08 EUR		50 %	290.08 EUR
[x]	FRONT BUMPER/CENTER/RIGHT			SCRATCH WITH PAINT DAMAGE		
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

1	2	3	4	5	6	7	8	9	10
115.56	290.08	63.00	0	0	0	0	0	0	0
115.56	145.04	63.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
178.56	290.08	0	468.64
HOG: 0	BG: 0		NA Deprec. 323.60
			0.00%
			TOTAL 323.60

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 02/11/2017 Hour : 10:45 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	