

D9LTJD

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	154128 KM
File nr. :	1456401	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPC562 / WBA3E11070J709471 /		yr of constructionr :	/
E-File nr. :		First registration :	12/09/2013
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	54847	Fuel :	
Classification :	G	Environment Class:	EURO 5
Customer company :	NETWORK RESEARCH BELGIUM	Co2:	109g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK			Service manual :			
Cert. of reg. / Part 1:	OK	[x]		Cert. of conformity :	OK		
Cert. of reg. copy / Part 2:				Insurance certificate :			
Warning vest :	OK	[x]		Transport licence :			
Tax certificate :				Navigation CD/SD/DVD	OK	[x]	
Fuel card :				Car radio :	OK	[x]	
Mobile phone kit :				Extinguisher :	OK	[x]	
				Warning triangle :	OK	[x]	
First aid kit :	OK	[x]		Oil level :	OK	[x]	
Jack, wheelspanner :	OK	[x]		Filled up :	0		

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :		

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	60	R	16	H
Rear tyre		205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR WINDOW STYLE/RIGHT/FRONT	OTHER DAMAGES	TE POLIEREN
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	

Interior

[x]	SEAT FL	STAIN
[x]	SEAT FR	STAIN

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	ROOF /FRONT/LEFT/CENTER		DENT			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	BONNET/CENTER/LEFT		OTHER DAMAGES		CHEMISCHE INWERKING	
			Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		290.08 EUR		50 %	290.08 EUR

1	2	3	4	5	6	7	8	9	10
290.08	63.00	0	0	0	0	0	0	0	0
145.04	63.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	290.08	0	353.08
HOG: 0	BG: 0		NA Deprec. 208.04
			0.00%
			TOTAL 208.04

APPRAISAL

www.vabfleetservices.be

Date : 09/11/2017

4/4

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 09/11/2017 Hour : 14:26	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	