

www.vabfleetservices.be Date: 09/11/2017 1/4

D8ZNRI

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
|------------------------------|-------------------|--------------------------|-------------------------------|
| Owner: | | Mileage : | 140302 KM |
| File nr. : | 1455903 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1EDW366 / YV1MV8481D2 | 018365 / | yr of constructionr : | / |
| E-File nr. : | | First registration : | 01/11/2012 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | VOLVO / V40 | Fuel type : | DIESEL |
| Object nr. : | 37802 | Fuel: | |
| Classification: | | Environment Class: | EURO 5 |
| Customer company : | KBC GROEP NV | Co2: | 94g/km |
| Driver : | | Remote controls: | 2 |
| Covering: | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan): | 0 |
| Vehicle type : | V40 D2 Base 115PK | Country registration : | BELGIUM |

| VAT over the margin - car: | No | Metallic paint: | Yes | | | | | | | |
|------------------------------|--------------------|---------------------|---------|--|--|--|--|--|--|--|
| Variant car: | BREAK | Engine size: | 1560 | | | | | | | |
| Gear box : | Manueel | Number of places: | 5 | | | | | | | |
| Number of gears: | 6 | Number of doors: | 5 | | | | | | | |
| HP: | 114 | kW: | 84 | | | | | | | |
| Fisc HP | | Imported vehicle: | | | | | | | | |
| Animals transported: | No | Smoked in vehicle: | No | | | | | | | |
| Due date vehicle inspection: | | Extra set of tires: | No | | | | | | | |
| | | Use: | Unknown | | | | | | | |
| | | | | | | | | | | |
| General condition: | General condition: | | | | | | | | | |



www.vabfleetservices.be Date: 09/11/2017 2/4

| Original registr. number : | OK | | Service manual : | OK | [x] |
|------------------------------|----|-----|-------------------------|----|-----|
| Cert. of reg. / Part 1: | | | Cert. of conformity: | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | | |
| Warning vest: | OK | [x] | Transport licence : | | |
| Tax certificate : | | | Navigation CD/SD/DVD | | [x] |
| Fuel card : | | | Car radio : | OK | [x] |
| Mobile phone kit : | | | Extinguisher : | OK | [x] |
| | | | Warning triangle : | OK | [x] |
| First aid kit : | OK | [x] | Oil level : | OK | [x] |
| Jack, wheelspanner : | OK | [x] | Filled up : | 0 | |

Wheels and tyres: Winter tires

| | | [x] W | idth | | | He | eight | | | Туре | | Rim | Index |
|------------|-----|-------------|-------|-----|----|-----|-------|------|-----|-----------------|---|-----------|-------|
| Wheel RES: | [x] | | Tyre: | | OK | | / | Rim: | | | | / Hubcap: | |
| Wheel RR: | [x] | UNIROYAL | Tyre: | | OK | [x] | 2-4 / | Rim: | | | | / Hubcap: | |
| Wheel FR: | [x] | BRIDGESTONE | Tyre: | [x] | OK | [x] | 2-4 / | Rim: | [x] | WHEEL SCRATCHED |) | / Hubcap: | |
| Wheel RL: | [x] | UNIROYAL | Tyre: | | OK | [x] | 2-4 / | Rim: | | | | / Hubcap: | |
| Wheel FL: | [x] | BRIDGESTONE | Tyre: | | OK | [x] | 2-4 / | Rim: | [x] | WHEEL SCRATCHED |) | / Hubcap: | |

| | [x] | Width | Height | Type | Rim | Index |
|------------|-----|-------|--------|------|-----|-------|
| Front tyre | ; | 205 | 55 | R | 16 | M+S |
| Rear tyre | | 205 | 55 | R | 16 | M+S |

Remark:

Wheels and tyres:

| Wheel FL: | Tyre: | OK | / | Rim: | / Hubcap: |
|------------|-------|----|---|------|-----------|
| Wheel RL: | Tyre: | OK | / | Rim: | / Hubcap: |
| Wheel FR: | Tyre: | OK | / | Rim: | / Hubcap: |
| Wheel RR: | Tyre: | OK | / | Rim: | / Hubcap: |
| Wheel RES: | Tyre: | OK | / | Rim: | / Hubcap: |
| | | | | | |

| [x] | Width | Height | Туре | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark:



Date: 09/11/2017 www.vabfleetservices.be 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

| В | od | y | W | or | ĸ | \& | Wi | nc | ot | WS | ò |
|---|----|---|---|----|---|----|----|----|----|----|---|
| | | | | | | | | | | | |

[x] REAR BUMPER/RIGHT/CORNER OTHER DAMAGES KLEURVERSCHIL

REAR DOOR/LEFT/CENTER [x]

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT BUMPER/LEFT OTHER DAMAGES SLECHTE HERSTELLING

Number Code Description Unit price Depr. **Total**

DENT

0

Others

RIM FRONT RIGHT

| N | lumber | Code | Description | Unit price | Depr. | Total |
|---|--------|-------------------|--------------------|------------|-------|-----------|
| 1 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|---|---|---|---|---|---|---|---|----|
| 95.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 95.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|------------------|
| 95.00 | 0 | 0 | 95.00 |
| HOG: 0 | BG: 0 | | NA Deprec. 95.00 |

0.00% TOTAL 95.00



09/11/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

| ANCES | | NORMAL CONCLUSION | | | | | |
|------------|--|---|---|--|--|--|--|
| 0 min | Waiting time: 0 Reason: | min | Towing time : Reason : | 0 min | | | |
| No | I | | | | | | |
| | | | | | | | |
| thout VAT | | | | | | | |
| | | E . II WAREL O | | | | | |
| | | executed by VAB Fleet S | ervices | | | | |
| ustomer : | | | | | | | |
| 09/11/2017 | Hour: 13:40 | | | | | | |
| | | | | | | | |
| et | | | | | | | |
| @ | | | | | | | |
| customer | | | | | | | |
| | | | | | | | |
| | 0 min No thout VAT stomer: 09/11/2017 et @ | 0 min Waiting time : 0 Reason : No Waiting time : 0 Reason : Waiting time : 0 Waiting time : 0 Reason : Waiting time : 0 Waiting time | No No Executed by VAB Fleet S og/11/2017 Hour: 13:40 et @ | 0 min Waiting time : 0 min Reason : Reason : No | | | |