

D7N6TZ

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	40601 KM
File nr. :	1454899	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1KPY995 / WDD1760121V068590 /		yr of constructionr :	/
E-File nr. :		First registration :	12/06/2015
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / A	Fuel type :	
Object nr. :	45735	Fuel :	
Classification :	N	Environment Class:	EURO 6
Customer company :	KPMG ADVISORY	Co2:	102g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

<b>Original registr. number :</b>	OK		<b>Service manual :</b>	OK	[x]
<b>Cert. of reg. / Part 1:</b>	OK	[x]	<b>Cert. of conformity :</b>	OK	
<b>Cert. of reg. copy / Part 2:</b>			<b>Insurance certificate :</b>		
<b>Warning vest :</b>	OK	[x]	<b>Transport licence :</b>		
<b>Tax certificate :</b>			<b>Navigation CD/SD/DVD</b>	OK	[x]
<b>Fuel card :</b>			<b>Car radio :</b>	OK	[x]
<b>Mobile phone kit :</b>			<b>Extinguisher :</b>	OK	[x]
			<b>Warning triangle :</b>	OK	[x]
<b>First aid kit :</b>	OK	[x]	<b>Oil level :</b>	OK	[x]
<b>Jack, wheelspanner :</b>	OK	[x]	<b>Filled up :</b>	0	

## Wheels and tyres: Summer tires

<b>Wheel FL :</b>	[x]	MICHELIN	<b>Tyre :</b>	OK	[x]	2-4 /	<b>Rim :</b>	/	<b>Hubcap :</b>		
<b>Wheel RL :</b>	[x]	MICHELIN	<b>Tyre :</b>	OK	[x]	2-4 /	<b>Rim :</b>	/	<b>Hubcap :</b>		
<b>Wheel FR :</b>	[x]	MICHELIN	<b>Tyre :</b>	[x]	OK	[x]	2-4 /	<b>Rim :</b>	/	<b>Hubcap :</b>	
<b>Wheel RR :</b>	[x]	MICHELIN	<b>Tyre :</b>	OK	[x]	2-4 /	<b>Rim :</b>	/	<b>Hubcap :</b>		
<b>Wheel RES:</b>	[x]		<b>Tyre :</b>	OK		/	<b>Rim :</b>	/	<b>Hubcap :</b>		

  

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

  

**Remark :**      4SEASONS BANDEN

### Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

  

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT

SCRATCH (WITHOUT PAINT DAMAGE)

[x] BONNET/CENTER/LEFT

DENT

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

## Prices in EUR without VAT

Authorized by customer :  Remark authorized customer :  Date : 07/11/2017      Hour : 08:59 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	