

APPRAISAL

www.vabfleetservices.be Date: 02/11/2017 1/4

D4RZQ3

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: DIRTY [x] EXT: CLEAN [x] Owner: Mileage : 117961 KM File nr. : Mileage start / arrival: 0 / 01452567 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1EGC010 / VF38D9HL0CL081393 / E-File nr. : First registration: 22/11/2012 Color: VFS-nr.: **BROWN** Make + Model : Fuel type : PEUGEOT / 508 **DIESEL** Object nr. : Fuel: 11927 Classification: **Environment Class:** EURO 5 Customer company: Co2: ALCATEL LUCENT 114g/km Driver : Remote controls: 1 TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: 508 BER Active 115PK Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	,	1	



APPRAISAL

www.vabfleetservices.be Date: 02/11/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICI	HELIN	Tyre:		OK	[x]	4-6 /	Rim:		/	Hubcap :	
Wheel RL:	[x]	MICI	HELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	MICI	HELIN	Tyre:	[x]	OK	[x]	4-6 /	Rim:	Rim: / Hubcap:			
Wheel RR:	[x]	MICI	HELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RES:	[x]			Tyre:		OK		/	Rim:		/	Hubcap:	
		[x]		Width			Н	eight	Ì	Туре		Rim	Index
Fro	nt tyre			215				60		R		16	Н
Rea	ar tyre			215				60		R		16	Н

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:

Remark:



Others

APPRAISAL

www.vabfleetservices.be Date: 02/11/2017 3/4

STATUS: NOT ACCEPTABLE

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 5	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		72.90 EUR

1	2	3	4	5	6	7	8	9	10
72.90	0	0	0	0	0	0	0	0	0
72.90	0	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
72.90		0	0	72.90
72.90	NA Deprec.		BG: 0	HOG: 0
	0.00%			
72.90	TOTAL			



APPRAISAL

4/4

02/11/2017 www.vabfleetservices.be Date: [x] = Status Modification **Pictures:** No **CIRCUMSTANCES** NORMAL CONCLUSION Extra Time : $0 \min$ Waiting time: 0 min Towing time : $0 \min$ Reason: Reason: NOT EXECUTED: No Reason: Remark: Prices in EUR without VAT Authorized by Executed by VAB Fleet Services customer : Remark authorized customer : Date: 02/11/2017 Hour: Company: Executed by VAB Fleet Services E-Mail: Signature authorized by customer