

www.vabfleetservices.be Date: 30/10/2017 1/4

D5C0YR

[X] EFFECTIVE	[ ] NOT EXECUTED	[ ] COLLECTION	[ ] DELIVERY
---------------	------------------	----------------	--------------

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	29584 KM
File nr. :	1453014	Mileage start / arrival:	0/0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LKC065 / SB1MS3JE50E196	5631 /	yr of constructionr :	/
E-File nr. :		First registration :	09/10/2015
VFS-nr. :		Color :	GREY
Make + Model :	TOYOTA / AURIS	Fuel type :	HYBRID
Object nr. :	39269	Fuel:	
Classification:		Environment Class:	EURO 6
Customer company :	TOYOTA MOTOR EUROPE	Co2:	91g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

Variant car:		Engine size:	1798
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	99	kW:	73
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 30/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :		
Jack, wheelspanner :			Filled up :	0	

## Wheels and tyres: Summer tires

<del> </del>	t tyre		225 225	1		45 45			R R		17 17	W
		[x]	Width			Height			Type		Rim	Index
Wheel RES:	[x]	ANDER	E Tyre:	Ok		/	Rim:			,	Hubcap:	
Wheel RR:	[x]	DUNLO	P Tyre:	Ok	[	[x] 4-6/	Rim:	: [x] WHEEL SCRATCHED / <b>Hubcap</b> :				
Wheel FR:	[x]	DUNLO	P Tyre:	[x] Ok	[	[x] 4-6/	Rim:	: [x] WHEEL SCRATCHED / Hubcap:				
Wheel RL:	[x]	DUNLO	P Tyre:	Ok	[	[x] 4-6/	Rim:			,	Hubcap:	
Wheel FL:	[x]	DUNLO	P Tyre:	Ok	[	[x] 4-6/	Rim :	[x]	WHEEL SCRATCHEI	Ο ,	Hubcap:	

# Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:

Remark:



www.vabfleetservices.be Date: 30/10/2017 3/4

### STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] FRONT MUDGUARD/LEFT/REAR DENT

[x] FRONT MUDGUARD/RIGHT/CENTER DENT

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

Interior

[x] BOOT LID IN SCRATCHED

### STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] WINDSCREEN/CENTER/RIGHT WINDOW DAMAGE

NumberCodeDescriptionUnit priceDepr.Total1I 1i-vab-herstr-01WINDOW REPAIR58.80 EUR58.80 EUR

#### Others

RIM FRONT RIGHT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

	1	2	3	4	5	6	7	8	9	10
	58.80	95.00	0	0	0	0	0	0	0	0
Γ	58.80	95.00	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
153.80	0	0	153.80
NA Deprec. 153.80		BG: 0	HOG: 0
0.000/			

0.00%
TOTAL 153.80



4/4

30/10/2017 www.vabfleetservices.be Date: [x] = Status Modification **Pictures:** No **CIRCUMSTANCES** NORMAL CONCLUSION Extra Time :  $0 \min$ Waiting time: 0 min Towing time :  $0 \min$ Reason: Reason: NOT EXECUTED: No Reason: Remark: Prices in EUR without VAT Authorized by Executed by VAB Fleet Services customer : Remark authorized customer : Date: 30/10/2017 Hour: 12:15 Company: Executed by VAB Fleet Services E-Mail: Signature authorized by customer