

DE906B

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	48034 KM
File nr. :	1460111	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1NVX838 / WBAWZ310400R74898 /		yr of constructionr :	/
E-File nr. :		First registration :	10/05/2016
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / X3	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	ONBEKEND	Co2:	130g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :			Service manual :		
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :			/	Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6 /	Rim :		/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :			/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	245	50	R	18	V
Rear tyre	245	50	R	18	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
	Repair paint - LI	New paint - E	Depr.	Total
3 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	58.32 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	GRIJS AFDEKKLEP	80.00 EUR	50 %	80.00 EUR

1	2	3	4	5	6	7	8	9	10
58.32	95.00	315.80	0	0	0	0	0	0	0
58.32	95.00	157.90	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
153.32	315.80	0	469.12
HOG: 0	BG: 0		NA Deprec. 311.22
			0.00%
			TOTAL 311.22

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 15/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	