

DBHC79

☒ EFFECTIVE    ☐ NOT EXECUTED    ☐ COLLECTION    ☐ DELIVERY

[x] = Status Modification

|                               |                               |                          |                               |
|-------------------------------|-------------------------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING               | Cleanliness :            | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner :                       |                               | Mileage :                | 46330 KM                      |
| File nr. :                    | 1457908                       | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                               | Mileag ref. service :    | 0                             |
| 1GRE842 / SB1ZS3JE00E076161 / |                               | yr of constructionr :    | /                             |
| E-File nr. :                  |                               | First registration :     | 01/01/1918                    |
| VFS-nr. :                     |                               | Color :                  | GREY                          |
| Make + Model :                | TOYOTA / AURIS TOURING SPORTS | Fuel type :              | HYBRID                        |
| Object nr. :                  | 39269                         | Fuel :                   |                               |
| Classification :              |                               | Environment Class:       |                               |
| Customer company :            | TOYOTA MOTOR EUROPE           | Co2:                     | g/km                          |
| Driver :                      |                               | Remote controls:         | 1                             |
| Covering :                    | TISSUE-LEATHER                | Number keys :            | 1 [x]                         |
| Vehicle kind :                | VEHICLE                       | Seats (minivan) :        | 0                             |
| Vehicle type :                |                               | Country registration :   | BELGIUM                       |

|                              |                   |                     |         |
|------------------------------|-------------------|---------------------|---------|
| VAT over the margin - car:   |                   | Metallic paint:     | Yes     |
| Variant car:                 | BREAK             | Engine size:        |         |
| Gear box :                   | Automaat algemeen | Number of places:   | 5       |
| Number of gears:             |                   | Number of doors:    | 5       |
| HP:                          |                   | kW:                 |         |
| Fisc HP                      |                   | Imported vehicle:   |         |
| Animals transported:         | No                | Smoked in vehicle:  | No      |
| Due date vehicle inspection: |                   | Extra set of tires: | No      |
|                              |                   | Use:                | Unknown |
| General condition:           |                   |                     |         |

|                              |                            |                         |    |     |
|------------------------------|----------------------------|-------------------------|----|-----|
| Original registr. number :   | OK                         | Service manual :        | OK | [x] |
| Cert. of reg. / Part 1:      | NOK [x] MISSING/INCOMPLETE | Cert. of conformity :   | OK |     |
| Cert. of reg. copy / Part 2: | [x]                        | Insurance certificate : |    |     |
| Warning vest :               | OK [x]                     | Transport licence :     |    |     |
| Tax certificate :            |                            | Navigation CD/SD/DVD    |    |     |
| Fuel card :                  |                            | Car radio :             | OK | [x] |
| Mobile phone kit :           |                            | Extinguisher :          | OK | [x] |
|                              |                            | Warning triangle :      | OK | [x] |
| First aid kit :              | OK [x]                     | Oil level :             | OK | [x] |
| Jack, wheelspanner :         |                            | Filled up :             | 0  |     |

## Wheels and tyres: Summer tires

|            |     |           |        |     |     |       |       |       |                 |                 |          |          |
|------------|-----|-----------|--------|-----|-----|-------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL:  | [x] | FIRESTONE | Tyre : | OK  | [x] | 4-6 / | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel RL : | [x] | DUNLOP    | Tyre : | OK  | [x] | 4-6 / | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel FR : | [x] | FIRESTONE | Tyre : | [x] | OK  | [x]   | 4-6 / | Rim : | [x]             | WHEEL SCRATCHED | /        | Hubcap : |
| Wheel RR : | [x] | DUNLOP    | Tyre : | OK  | [x] | 4-6 / | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel RES: | [x] | ANDERE    | Tyre : | OK  |     | /     | Rim : |       |                 | /               | Hubcap : |          |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225   | 45     | R    | 17  | W     |
| Rear tyre  | 225   | 45     | R    | 17  | W     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |  |   |          |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork l& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR BUMPER/SIDE/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork l& windows

[x] REAR MUDGUARD/RIGHT/FRONT DENT

|   |                  | Repair paint - LI | New paint - E | Depr. | Total      |
|---|------------------|-------------------|---------------|-------|------------|
| 1 | 10 LU =48.00 EUR | 369.84 EUR        |               | 50 %  | 417.84 EUR |

[x] REAR DOOR/RIGHT/CORNER/BELOW SCRATCH WITH PAINT DAMAGE

|   |                | Repair paint - LI | New paint - E | Depr. | Total      |
|---|----------------|-------------------|---------------|-------|------------|
| 1 | 0 LU =0.00 EUR | 382.02 EUR        |               | 50 %  | 382.02 EUR |

[x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

|   |                | Repair paint - LI | New paint - E | Depr. | Total      |
|---|----------------|-------------------|---------------|-------|------------|
| 1 | 0 LU =0.00 EUR | 382.02 EUR        |               | 50 %  | 382.02 EUR |

### Accessories and others

[x] ANTENNA MISSING/INCOMPLETE

|   |                | Repair paint - LI | New paint - E | Depr. | Total |
|---|----------------|-------------------|---------------|-------|-------|
| 3 | 0 LU =0.00 EUR | 0 EUR             |               | 50 %  |       |

### Others

RIM FRONT LEFT

| Number | Code                  | Description        | Unit price | Depr. | Total     |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 2      | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

RIM REAR LEFT

| Number | Code                  | Description        | Unit price | Depr. | Total     |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 2      | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

RIM REAR RIGHT

| Number | Code                  | Description        | Unit price | Depr. | Total     |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 2      | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code | Description       | Unit price         | Depr.     | Total     |
|--------|------|-------------------|--------------------|-----------|-----------|
| 2      | I 1  | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

## Pieces

| Number | Code | Description | Unit price | Depr. | Total     |
|--------|------|-------------|------------|-------|-----------|
| 3      | 1    | ANTENNE     | 18.00 EUR  | 50 %  | 18.00 EUR |

| 1       | 2      | 3     | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|---------|--------|-------|---|---|---|---|---|---|----|
| 1181.88 | 380.00 | 18.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| 590.94  | 380.00 | 9.00  | 0 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                   |
|------------|-------------|---------|-------------------|
| 380.00     | 1199.88     | 0       | 1579.88           |
| HOG: 0     | BG: 2       |         | NA Deprec. 979.94 |
|            |             |         | 0.00%             |
|            |             |         | TOTAL 979.94      |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                               |                                  |                                 |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min            | Waiting time : 0 min<br>Reason : | Towing time : 0 min<br>Reason : |
| NOT EXECUTED : No<br>Reason : |                                  |                                 |
| Remark :                      |                                  |                                 |

## Prices in EUR without VAT

|                                                                                                                                                                      |                                |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| Authorized by customer :<br><br>Remark authorized customer :<br><br>Date : 15/11/2017      Hour : 10:29<br>Company :<br>Executed by VAB Fleet Services<br>E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>                                              |                                |