

DBLV20

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	92537 KM
File nr. :	1457999	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FLB679 / W0LPD8EW7D8075640 /		yr of constructionr :	/
E-File nr. :		First registration :	02/08/2013
VFS-nr. :		Color :	BLACK
Make + Model :	OPEL / ASTRA BREAK	Fuel type :	DIESEL
Object nr. :	1FLB679	Fuel :	
Classification :	O	Environment Class:	EURO 5
Customer company :	SIEMENS NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ASTRA BRE ecoFL.Enjoy Active St/St 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1686
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:	
--------------------	--

<b>Original registr. number :</b>	OK			<b>Service manual :</b>	OK	[x]
<b>Cert. of reg. / Part 1:</b>				<b>Cert. of conformity :</b>	OK	
<b>Cert. of reg. copy / Part 2:</b>	OK	[x]		<b>Insurance certificate :</b>		
<b>Warning vest :</b>				<b>Transport licence :</b>		
<b>Tax certificate :</b>				<b>Navigation CD/SD/DVD</b>		
<b>Fuel card :</b>				<b>Car radio :</b>	OK	[x]
<b>Mobile phone kit :</b>				<b>Extinguisher :</b>	OK	[x]
				<b>Warning triangle :</b>	OK	[x]
<b>First aid kit :</b>	OK	[x]		<b>Oil level :</b>	OK	[x]
<b>Jack, wheelspanner :</b>				<b>Filled up :</b>	0	

## Wheels and tyres: Summer tires

<b>Wheel FL :</b>	[x]	GOODYEAR	<b>Tyre :</b>	OK	[x]	2-4 /	<b>Rim :</b>		/	<b>Hubcap :</b>	
<b>Wheel RL :</b>	[x]	GOODYEAR	<b>Tyre :</b>	OK	[x]	2-4 /	<b>Rim :</b>		/	<b>Hubcap :</b>	
<b>Wheel FR :</b>	[x]	GOODYEAR	<b>Tyre :</b>	[x]	OK	[x]	2-4 /	<b>Rim :</b>		/	<b>Hubcap :</b> [x] SCRATCHED
<b>Wheel RR :</b>	[x]	GOODYEAR	<b>Tyre :</b>	OK	[x]	2-4 /	<b>Rim :</b>		/	<b>Hubcap :</b>	
<b>Wheel RES:</b>	[x]		<b>Tyre :</b>	OK		/	<b>Rim :</b>		/	<b>Hubcap :</b>	

  

	[x]	<b>Width</b>	<b>Height</b>	<b>Type</b>	<b>Rim</b>	<b>Index</b>
<b>Front tyre</b>		215	60	R	16	V
<b>Rear tyre</b>		215	60	R	16	V

  

**Remark :**

### Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

  

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE
-----	--------------------	---------------------------

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	0	0	0	0	0	0	0	0	0
105.90	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	211.80	0	211.80
HOG: 0	BG: 0		NA Deprec. 105.90
			0.00%
			TOTAL 105.90

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

## Prices in EUR without VAT

Authorized by customer :  Remark authorized customer :  Date : 14/11/2017      Hour : 14:46 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	