

D1APXA

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: EXT: CLEAN [x]
Owner :		Mileage :	130528 KM
File nr. :	1449819	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HAG023 / VF1JZ14P650565490 /		yr of constructionr :	/
E-File nr. :		First registration :	12/06/2014
VFS-nr. :		Color :	BURGUNDY
Make + Model :	RENAULT / SCENIC	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :	N	Environment Class:	
Customer company :	WRAK KBC REMARKETING	Co2:	g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	NOK	Insurance certificate :	OK
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
		Warning triangle :	OK
First aid kit :	OK	Oil level :	
Jack, wheelspanner :		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	CONTINENTAL	Tyre :	OK	2-4 /	Rim :		/	Hubcap :	
Wheel RL :	CONTINENTAL	Tyre :	OK	2-4 /	Rim :	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	CONTINENTAL	Tyre :	OK	2-4 /	Rim :	WHEEL SCRATCHED	/	Hubcap :	
Wheel RR :	CONTINENTAL	Tyre :	OK	2-4 /	Rim :	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	ANDERE	Tyre :	OK	4-6 /	Rim :		/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	17	V
Rear tyre	205	55	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0		0	
Rear tyre	0	0		0	

Remark :

Conclusion

Bodywork \& windows

REAR DOOR/RIGHT/CENTER

OTHER DAMAGES

HERST OVBH

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

REAR BUMPER/CENTER/RIGHT

SCRATCH WITH PAINT DAMAGE

REAR MUDGUARD/LEFT/CENTER

DENT

REAR MUDGUARD/LEFT/FRONT

SCRATCH (WITHOUT PAINT DAMAGE)

REAR MUDGUARD/RIGHT/CENTER

DENT

REAR DOOR/RIGHT/REAR

SCRATCH (WITHOUT PAINT DAMAGE)

REAR DOOR/RIGHT/CORNER/BELOW

SCRATCH WITH PAINT DAMAGE

INSTAP

REAR THRESHOLD/RIGHT/REAR

DENT

+ KRAS

REAR DOOR/RIGHT/FRONT

SCRATCH WITH PAINT DAMAGE

REAR THRESHOLD/RIGHT/FRONT

DENT

FRONT DOOR/RIGHT/REAR

DENT

FRONT MUDGUARD/LEFT/CENTER

SCRATCH (WITHOUT PAINT DAMAGE)

BONNET/CENTER/LEFT

SCRATCH (WITHOUT PAINT DAMAGE)

FRONT MUDGUARD/RIGHT/CENTER

SCRATCH (WITHOUT PAINT DAMAGE)

Interior

BOOT LID IN

CARVED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

REAR DOOR/CENTER/LEFT

OTHER DAMAGES

Number Code

Description

Unit price

Depr.

Total

0 0

REAR MUDGUARD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE			
Number	Code	Description	Unit price	Depr.	Total
0	0				

REAR BUMPER/SIDE/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE			
Number	Code	Description	Unit price	Depr.	Total
0	0				

REAR MUDGUARD/RIGHT/FRONT		DENT			
Number	Code	Description	Unit price	Depr.	Total
0	0				

REAR THRESHOLD/LEFT/REAR		DENT			
Number	Code	Description	Unit price	Depr.	Total
0	0				

REAR DOOR/LEFT/CENTER		DENT	DEUK+KRASSEN +FLANFBESCHERMER		
Number	Code	Description	Unit price	Depr.	Total
0	0				

FRONT DOOR/LEFT/REAR		DENT			
Number	Code	Description	Unit price	Depr.	Total
0	0				

FRONT DOOR/RIGHT/CENTER			OTHER DAMAGES		CHEM INW	
Number	Code	Description	Unit price	Depr.	Total	
0	0					

FRONT WHEEL/RIGHT		OTHER DAMAGES		MODDERKUIP	
Number	Code	Description	Unit price	Depr.	Total
0	0				

Number		Code	Description	Unit price	Depr.	Total
0	0					

[illegible]

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : EXP ONDERGRONDSE P		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	