

D7GHY7

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	124716 KM
File nr. :	1454745	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DRH528 / VF3XU9HM0CZ038167 /		yr of constructionr :	/
E-File nr. :		First registration :	01/08/2012
VFS-nr. :		Color :	WHITE
Make + Model :	PEUGEOT / EXPERT	Fuel type :	DIESEL
Object nr. :	72417	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CEGELEC BUILDING SERVICES	Co2:	177g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	EXPERT B/F MWB 229 L2H1 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	1560
Gear box :	Manueel	Number of places:	3
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	DUNLOP	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	
Rear tyre	215	60	R	16	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT BUMPER/RIGHT DENT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	110.64 EUR

Interior

[x] SEAT FL HOLE

Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR	64.32 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	45.88 EUR

1	2	3	4	5	6	7	8	9	10
45.88	110.64	64.32	0	0	0	0	0	0	0
45.88	110.64	64.32	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
220.84	0	0	220.84
HOG: 0	BG: 3		NA Deprec. 220.84
			0.00%
			TOTAL 220.84

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	