

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	124599 KM
File nr. :	1457630	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1JAP450 / SB1ZS3JE80E127759 /		yr of constructionr :	/
E-File nr. :		First registration :	18/11/2014
VFS-nr. :		Color :	WHITE
Make + Model :	TOYOTA / AURIS TOURING SPORTS	Fuel type :	HYBRID
Object nr. :	55480	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	92g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:		Engine size:	1798
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	99	kW:	73
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:			Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	DUNLOP	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	DUNLOP	Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	45	R	17	W
Rear tyre	225	45	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT			SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		254.16 EUR		50 %	254.16 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER			SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR		369.84 EUR		50 %	369.84 EUR
[x]	WINDSCREEN/CENTER/RIGHT			WINDOW DAMAGE		
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR

Interior

[x]	BOOT LID IN	CARVED			
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	BROKEN / CRACKED			
		Repair paint - LI	New paint - E	Depr.	Total
5	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

RIM FRONT RIGHT						
Number	Code	Description	Unit price	Depr.	Total	
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	UPHOLSTERY DOOR	108.00 EUR	50 %	108.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	SIDE INDICATOR	7.20 EUR	50 %	7.20 EUR

1	2	3	4	5	6	7	8	9	10
132.00	58.80	254.16	369.84	31.20	95.00	0	0	0	0
66.00	58.80	127.08	184.92	15.60	95.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
153.80	787.20	0	941.00
HOG: 0	BG: 2		NA Deprec. 547.40
			0.00%
			TOTAL 547.40

APPRAISAL

www.vabfleetservices.be

Date : 10/11/2017

5/5

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min 	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 10/11/2017 Hour : 13:22	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	