

D9GT6B

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	103850 KM
File nr. :	1456296	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DKC674 / VF1JZ00BD47295782 /		yr of constructionr :	/
E-File nr. :		First registration :	07/06/2012
VFS-nr. :		Color :	SILVER
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :	47067	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Atos Belgium NV	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.SCENIC Energ.Privilege 7pl.FAP 130PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1598
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :		
Warning vest :	OK	[x]		Transport licence :		
Tax certificate :				Navigation CD/SD/DVD	OK	[x]
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :			/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :			/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	55	R	17	M+S
Rear tyre		205	55	R	17	M+S

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/FRONT

SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT

DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR			211.80 EUR

[x] FRONT MUDGUARD/LEFT/FRONT

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] FRONT BUMPER/LEFT

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE

BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
3 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	INDICATOR	15.00 EUR	50 %	15.00 EUR

1	2	3	4	5	6	7	8	9	10
431.98	211.80	39.00	0	0	0	0	0	0	0
215.99	211.80	19.50	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	682.78	0	682.78
HOG: 0	BG: 0		NA Deprec. 447.29
			0.00%
			TOTAL 447.29

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/11/2017 Hour : 08:52 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	