

DD2566

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	84719 KM
File nr. :	1459149	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPI497 / TMBJG9NE1E0052589 /		yr of constructionr :	/
E-File nr. :		First registration :	13/09/2013
VFS-nr. :		Color :	GREY
Make + Model :	SKODA / OCTAVIA BREAK	Fuel type :	DIESEL
Object nr. :	47002	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	AMCOR FLEXIBLES TRANSPAC BVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	OCTAVIA COMBI Ambition 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :		
			Warning triangle :	OK	[x]
First aid kit :			Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap : [x] MISSING/INCOMPLETE
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :	
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	>6 /	Rim :		/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	55	R	16	V
Rear tyre		205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/REAR DENT

[x] REAR DOOR/RIGHT/CENTER DENT

STATUS: NOT ACCEPTABLE

Others

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
30.00	0	0	0	0	0	0	0	0	0
15.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	30.00	0	30.00
HOG: 0	BG: 0		NA Deprec. 15.00
			0.00%
			TOTAL 15.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DARK

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 15/11/2017 Hour : 15:03 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	