



PEUGEOT 4008: 1GRS193

Vinnnumber:	VF3BU6HZBEZ804339	Versionname:	4008 Allure 150PK
First Registrationdate:	10/04/2014	Fiscalpower:	
Expertise Mileage:	135704	Power Kw:	110
Bodytype:	SUV	Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2610
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Panoramic roof
Windows electric F		Central consol F
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

225/55/18/98 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	1012,91
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	24,00



Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L polished, Scratch(es), Acceptable	0,00

No pictures to display	
Bonnet, Stone chip(s), Acceptable	0,00
No pictures to display	
Wing F R, Scratch(es), Lt - Spot repair	115,56
 	
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
 	
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Stone chip(s), Acceptable	0,00
No pictures to display	
Parcel shelf covering, Missing, E - Replace	75,00
 	
Roof pillar R, Bump(s), PDR - Knock out without painting	63,00
 	
Tailgate, Bump(s), PDR - Knock out without painting	142,20
  	
 	
Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
  	
Bonnet, Bump(s), PDR - Knock out without painting	63,00
 	