



OPEL Zafira: 1EGT754			
Vinnumber:	W0LPD9EM9D2028813	Versionname:	ZAFIRA TOURER
First Registrationdate:	28/11/2012	Fiscalpower:	ecoFL Enjoy St/St.130PK
Expertise Mileage:	135864	Power Kw:	96
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4116
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear			
Summer tyres:	225/50/17/94 Y Steel		
	Fr.L.	Continental: 4 mm	Fr.R.
		Continental: 4 mm	
	Re.L.	Continental: 5 mm	Re.R.
		Continental: 5 mm	

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			0,00
Front bumper, Scratch(es), LI - Repair and paint (complete)			0,00



Door F R, Scratch(es), LI - Repair and paint (complete)			0,00
---	--	--	------




Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel covers (all), Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00



Roof pillar L, Bump(s), PDR - Knock out without painting	0,00
--	------



Door panel R L, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), Acceptable	0,00



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------



Door panel R R, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Bump(s), PDR - Knock out without painting	0,00



Floor covering F L, Damaged, Smart repair

0,00

