



VOLVO V40: 1EHG226			
Vinnnumber:	YV1MV8481D2026407	Versionname:	V40 D2 Base 115PK
First Registrationdate:	3/12/2012	Fiscalpower:	
Expertise Mileage:	114632	Power Kw:	84
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	113686 KM		
Maintenance	OK		
Maintenance	28-11-2017		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear			
Winter tyres:	205/55/16/91 T LightMetal		
	Fr.L.	Continental: 5 mm	Fr.R.
	Re.L.	Continental: 6 mm	Re.R.
		Continental: 5 mm	Continental: 6 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	190,00
Bumper R, Scratch(es), Acceptable	0,00



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------




Door R L, Damaged, I - Repair	0,00
-------------------------------	------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

