



AUDI A5: 1GFM655

Vinnumber:	WAUZZZ8T5EA044218	Versionname:	
First Registrationdate:	24/01/2014	Fiscalpower:	
Expertise Mileage:	40448	Power Kw:	110
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	+12 dagen	Parking lot	3808
Battery functioning	Yes		
Number of doors	5		
Number of seats	4		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/50/17/94 Y LightMetal			
Summer tyres:	Fr.L.	Pirelli: 2 mm	Fr.R.	Pirelli: 2 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
Total cost ex VAT			400,56
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00



Door R R, Repaired, Acceptable	0,00
--------------------------------	------



Bumper corner R L, Scratch(es), It - Spot repair	115,56
--	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Backrest cover F L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F R, Repaired, Acceptable	0,00
--------------------------------	------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display