



VOLKSWAGEN Golf: MF5412				
Vinnumber:	WVWZZZAUZFW008295	Versionname:	GOLF BER Comfortline DSG 150PK Aut.	
First Registrationdate:	25/06/2014	Fiscalpower:		
Expertise Mileage:	127048	Power Kw:	110	
Bodytype:	Hatchback	Body color	White	
Gearbox:	Automatic	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	1627	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Adaptive cruise control				
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Sound engine	OK	
Idle position	OK	Clutch test	OK	
Engine startingtime	OK	Wiper fluid level	OK	
Exhaust gass	OK	Lighting	OK	
Transmission	OK	Wiperblades	OK	
Handbrake	OK			
Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			811,98	
Wing R L, Scratch(es), Acceptable			0,00	
No pictures to display				
Door R L, Scratch(es), Acceptable			0,00	
No pictures to display				
Wing F L, Scratch(es), LI - Repair and paint (complete)			220,18	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00	



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

