



RENAULT Grand Scenic: 1FUI367			
Vinnnumber:	VF1JZ14P649871460	Versionname:	GRAND SCENIC Energy Life 7pl.110PK
First Registrationdate:	28/10/2013	Fiscalpower:	
Expertise Mileage:	100330	Power Kw:	81
Bodytype:	MPV	Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3704
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	205/60/16/96 MS LightMetal			
	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 3 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			3161,47
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00



Bumper R, Bump(s) and scratch(es), Le - Replace and paint	651,00
---	--------





Floor covering R, Burned, Smart repair 64,32



Door R R, Bump(s), LI - Repair and paint (complete) 354,35



Floor covering R, Burned, Smart repair 64,32



Backrest cover F L, Burned, Smart repair 64,32



Door trim F R, Scratch(es), Smart repair 110,64



Seat cover F R, Burned, Smart repair 64,32



Floor covering F L, Burned, Smart repair 64,32



Seat cover R L, Burned, Smart repair 64,32



Seat cover F L, Burned, E - Replace 360,00



Sill outer R, Scratch(es), LI - Repair and paint (complete)

310,50



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Bump(s), Acceptable

0,00

No pictures to display

Bumper F L, Scratch(es), It - Spot repair

115,56



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Rearview mirror R complete, Damaged, Forfeit

12,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

