



BMW 5: BC5769

Vinnnumber:	WBA5L31000G078084	Versionname:	5 TOURING 520dA 190PK Aut.
First Registrationdate:	6/01/2016	Fiscalpower:	
Expertise Mileage:	61510	Power Kw:	140
Bodytype:	Break	Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2121
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Seats electric F L
GPS storage	HD	Seats electric F R
Windows electric F		Seats R ventilated
Windows electric R		Sun Roof electric
Cruise Control		Panoramic roof
Steering wheel multifunctional		Central consol F
Radio multimedia		Luggage cover
Type of headlighting	Headlighting Xenon	Front parking sensors
Type of GPS	GPS big screen color	Rear parking sensors
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Head-up Display		
Adaptive cruise control		
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

Winter tyres:	245/45/18/100 V LightMetal			
	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		1023,49
Front bumper, Bump(s) and scratch(es), It - Spot repair		115,56




Bodywork, Damaged, Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Bonnet, Scratch(es), LI - Repair and paint (complete)	348,09
---	--------



Maintenance book, Missing, E - Replace	0,00
--	------

No pictures to display

Interior, Damaged, Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

