



CITROEN BERLINGO: 1LBV370

Vinnumber:	VF77B9HFOEN539290	Versionname:	BERLINGO
First Registrationdate:	1/12/2014	Fiscalpower:	
Expertise Mileage:	111554	Power Kw:	66
Bodytype:		Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	3528
Battery functioning	Yes		
Number of doors	5		
Number of seats	3		
Number head rests	3		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1116,92
Wheel cover F R, Broken, E - Replace	22,50



Wheel cover R L, Scratch(es), E - Replace	22,50
---	--------------



Door F R, Scratch(es), LI - Repair and paint (complete)	238,76
---	---------------

			Interior, Dirty, Cleaning	48,00
			Maintenance, Maintenance, Execute	0,00
No pictures to display			Wheel cover F L, Scratch(es), E - Replace	22,50
			Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
			Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
			Roof, Bump(s) and scratch(es), Acceptable	0,00
No pictures to display			Bumper R, Bump(s) and scratch(es), E - Replace	329,40
			Door panel F R, Scratch(es), Smart repair	110,64
			Door trim F R, Scratch(es), E - Replace	91,50
				