


VOLVO V40: 1EJR607

Vinnnumber:	YV1MV8481D2028813	Versionname:	V40 D2 Base 115PK
First Registrationdate:	1/01/2013	Fiscalpower:	
Expertise Mileage:	114873	Power Kw:	84
Bodytype:	Hatchback	Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3514
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	306,80
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Damaged, LI - Repair and paint (complete)	211,80



Wing R R, Bump(s), Acceptable

0,00

No pictures to display