


BMW 1: 1FWH026

Vinnnumber:	WBA1C910X0J518218	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	18/11/2013	Fiscalpower:	
Expertise Mileage:	141410	Power Kw:	85
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	-2800	Parking lot	1215
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

Summer tyres:	205/55/16/91 W LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	817,80
-------------------	---------------


Windscreen, Stone chip(s), Windscreen repair	88,20
--	--------------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------

			Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
			Roof, Bump(s), PDR - Knock out without painting	82,80
			Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
			Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
			Door R R, Bump(s), Acceptable	0,00
No pictures to display				
			Ignition key, Missing, E - Replace	150,00