



| FORD K+: 1STA263                  |                   |              |           |
|-----------------------------------|-------------------|--------------|-----------|
| Vinnumber:                        | MAJUXXMTKUHP08399 | Versionname: |           |
| First Registrationdate:           |                   | Fiscalpower: |           |
| Expertise Mileage:                | 8204              | Power Kw:    | 63        |
| Bodytype:                         | Hatchback         | Body color   | White     |
| Gearbox:                          | MAN 5 VIT         | Paint type   | Metalic   |
| Transmission:                     |                   | Rims summer  | Aluminium |
| Fueltype:                         | Petrol            | Oil level    | OK        |
| Battery functioning               | Yes               | Parking lot  | 1404      |
| Number of doors                   | 5                 |              |           |
| Number of seats                   | 5                 |              |           |
| Number head rests                 | 5                 |              |           |
| Rims summer                       | Aluminium         |              |           |
| Category                          | Passenger Car     |              |           |
| Oil level                         | OK                |              |           |
| Registration Certificate Car (BE) | Yes               |              |           |

| Options                        |                        |
|--------------------------------|------------------------|
| Radio CD                       | Luggage cover          |
| Windows electric F             | Rear parking sensors   |
| Windows electric R             |                        |
| Cruise Control                 |                        |
| Steering wheel multifunctional |                        |
| Radio multimedia               |                        |
| Type of headlighting           | Headlighting Halogen   |
| Type of Lining                 | Lining Alcantara       |
| Type of climate control        | Manual climate control |

| Limited Technical Inspection |    |                     |     |
|------------------------------|----|---------------------|-----|
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Sound engine        | OK  |
| Idle position                | OK | Clutch test         | OK  |
| Engine startingtime          | OK | Wiper fluid level   | OK  |
| Exhaust gass                 | OK | Lighting            | OK  |
| Transmission                 | OK | Wiperblades         | OK  |
| Handbrake                    | OK |                     |     |

| Degree of wear |                           |                   |       |                   |
|----------------|---------------------------|-------------------|-------|-------------------|
| Summer tyres:  | 195/55/15/58 V LightMetal |                   |       |                   |
|                | Fr.L.                     | Continental: 6 mm | Fr.R. | Continental: 6 mm |
|                | Re.L.                     | Continental: 7 mm | Re.R. | Continental: 7 mm |

| Assistance equipment |     |
|----------------------|-----|
| Spare tyre compact   | Yes |

|                           |        |
|---------------------------|--------|
| Total cost ex VAT         | 439,44 |
| Interior, Dirty, Cleaning | 25,00  |



|                                                         |        |
|---------------------------------------------------------|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 169,44 |
|---------------------------------------------------------|--------|





|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|



|                                    |        |
|------------------------------------|--------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|--------|

No pictures to display