



MERCEDES B: 1GC S528

|                                   |                   |              |                |
|-----------------------------------|-------------------|--------------|----------------|
| Vinnumber:                        | WDD2462431J230276 | Versionname: | B 200 BE 156PK |
| First Registrationdate:           | 2/01/2014         | Fiscalpower: |                |
| Expertise Mileage:                | 36263             | Power Kw:    | 115            |
| Bodytype:                         | Hatchback         | Body color   | Grey           |
| Gearbox:                          | MAN 6 VIT         | Paint type   | Metalic        |
| Transmission:                     | Front             | Rims summer  | Aluminium      |
| Fueltype:                         | Petrol            | Oil level    | OK             |
| Battery functioning               | Yes               | Parking lot  | 1630           |
| Number of doors                   | 5                 |              |                |
| Number of seats                   | 5                 |              |                |
| Number head rests                 | 5                 |              |                |
| Rims summer                       | Aluminium         |              |                |
| Category                          | Passenger Car     |              |                |
| Oil level                         | OK                |              |                |
| Registration Certificate Car (BE) | Yes               |              |                |

Options

|                              |                       |                       |
|------------------------------|-----------------------|-----------------------|
| Radio CD                     |                       | Seats electric F L    |
| GPS storage                  | HD                    | Sun Roof electric     |
| Windows electric F           |                       | Panoramic roof        |
| Windows electric R           |                       | Central consol F      |
| Cruise Control               |                       | Luggage cover         |
| Steering wheel multifunction |                       | Front parking sensors |
| Type of headlighting         | Headlighting Halogen  | Rear parking sensors  |
| Type of Lining               | Lining fabrics        |                       |
| Type of climate control      | Autom climate control |                       |

Limited Technical Inspection

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Sound engine        | OK  |
| Idle position       | OK | Clutch test         | OK  |
| Engine startingtime | OK | Wiper fluid level   | OK  |
| Exhaust gass        | OK | Lighting            | OK  |
| Transmission        | OK | Wiperblades         | OK  |
| Handbrake           | OK |                     |     |

Degree of wear

|               |                           |               |       |               |
|---------------|---------------------------|---------------|-------|---------------|
|               | 205/55/16/91 T LightMetal |               |       |               |
| Winter tyres: | Fr.L.                     | Pirelli: 5 mm | Fr.R. | Pirelli: 5 mm |
|               | Re.L.                     | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

Assistance equipment

|            |     |            |     |
|------------|-----|------------|-----|
| Repair kit | Yes | Compressor | Yes |
|------------|-----|------------|-----|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 286,80 |
|-------------------|--------|

|                                                         |        |
|---------------------------------------------------------|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---------------------------------------------------------|--------|



|                                       |      |
|---------------------------------------|------|
| Windscreen, Stone chip(s), Acceptable | 0,00 |
|---------------------------------------|------|

|                        |  |
|------------------------|--|
| No pictures to display |  |
|------------------------|--|

|                                |      |
|--------------------------------|------|
| Door R L, Repaired, Acceptable | 0,00 |
|--------------------------------|------|

No pictures to display

|                                                                                    |       |
|------------------------------------------------------------------------------------|-------|
| Interior, Dirty, Cleaning                                                          | 75,00 |
|  |       |
| Alloy rim F R, Scratch(es), Acceptable                                             | 0,00  |
| No pictures to display                                                             |       |
| Door R R, Repaired, Acceptable                                                     | 0,00  |
| No pictures to display                                                             |       |